

Sequence IVB Sub-Groups | MINUTES

REVISION DATE: 5/19/2018 5:23:00 PM

Relevant Test:	Sequence IVB
Note Taker:	Chris Mileti
Meeting Date:	05-08-2018
Comments:	This was a back-to-back conference call with the two Sequence IVB Sub-Groups – IVB Procedure Review Sub-Group and IVB Precision/Operations Sub-Group .

1. IVB PRECISION/OPERATIONS SUB-GROUP:

1.1. Opening Comments from Afton:

- 1.1.1. Katerina Pecinovsky will be moving to another area of the company.
- 1.1.2. Ben Maddock will be the new engineer that is transitioning into her role.

1.2. Comments from Surveillance Panel Chairman:

- 1.2.1. Last week, the LG Group issued a new motion to accept the Sequence IVB test into GF-6.
 - 1.2.1.1. Toyota and ILSAC find this motion to be acceptable.
 - 1.2.1.2. This motion may be approved by the AOAP panel this week.
- 1.2.2. New Surveillance Panel Action Items:**
 - 1.2.2.1. The Surveillance Panel will need to meet within the next 1-2 weeks.
 - 1.2.2.2. The Panel needs to make a recommendation to the ACC regarding a registration date.
 - 1.2.2.3. The Panel will need to approve whether retroactive registration can be granted to tests that used Batch-C and Batch-D camshafts.
 - 1.2.2.4. The Panel will need to discuss the upcoming BOI/VGRA matrix.

1.2.3. Goal of the IVB Precision/Operations Sub-Group:

- 1.2.3.1. The purpose of this sub-group is to enhance the precision of this test.

1.3. Individual Laboratory Updates:

1.3.1. Update from Intertek:

- 1.3.1.1. NO_x Analysis:
 - 1.3.1.1.1. Exhaust gas NO_x was an important parameter during the development of the Sequence VE, VG and IVA tests.
 - 1.3.1.1.2. It may be useful to measure NO_x levels with the Sequence IVB.
 - 1.3.1.1.3. However, they cautioned that the highly dynamic nature of the IVB test cycle may make this difficult.
 - 1.3.1.1.4. They are currently running a trial with an ECM NO_x meter on IAR165.
 - 1.3.1.1.5. This is the same sensor that is used on the Sequence III.
 - 1.3.1.1.6. IAR165 is currently running its 2nd reference test to calibrate the stand.
 - 1.3.1.1.7. The goal of this trial is to measure how much the NO_x level changes over a 200HR test, and determine how much drift there is from test-to-test.
- 1.3.1.2. Analyze Blowby Gas Composition:

- 1.3.1.2.1. Intertek proposes analyzing the IVB blowby gas using Gas Chromatography / Mass Spectrometry.
- 1.3.1.2.2. The Panel will need to decide how to sample this material.
- 1.3.1.2.3. It will also need to determine if the gas and/or the liquid will be analyzed.
- 1.3.1.3. Hardware Magnetism:
 - 1.3.1.3.1. Intertek is measuring the change in magnetism of the camshafts and lifters from the start-of-test to the end-of-test.
 - 1.3.1.3.2. They questioned whether this magnetism plays a role in camshaft lobe failures.
 - 1.3.1.3.3. They have found that some E.O.T. lifters become so magnetized that they attract paperclips.
 - 1.3.1.3.4. Afton commented that the ISM test focuses on magnetism because its pass/fail parameter is weight loss.
 - 1.3.1.3.4.1. As a result, all critical hardware is degaussed before and after the test.
- 1.3.1.4. Silicone Variation from Lab-to-Lab:
 - 1.3.1.4.1. Lubrizol uses a single OEM rocker arm cover for all its break-in cycles.
 - 1.3.1.4.1.1. Lubrizol also tends to have the lowest silicone levels during break-in and aging.
 - 1.3.1.4.2. Intertek has previously used a new rocker arm cover for all its break-in cycles.
 - 1.3.1.4.2.1. This may be why Intertek's silicone typically peaks at a higher level (125-150ppm) than it does at Lubrizol.
 - 1.3.1.4.3. They just ran a trial with a used OEM rocker cover (like Lubrizol does) and the peak silicone dropped to 104ppm.
 - 1.3.1.4.4. Silicone may be leaching from the spark plug tube seals of the new OEM rocker arm covers.
 - 1.3.1.4.5. In fact, silicone may be leaching from new spark plug tube seals that are installed in the OHT rocker arm cover.
 - 1.3.1.4.5.1. The Surveillance Panel needs to investigate this further.
- 1.3.1.5. Iron Content from Test-to-Test:
 - 1.3.1.5.1. They would like the Surveillance Panel to look at the cumulative iron of an engine over its full life cycle.
 - 1.3.1.5.2. *Does this cumulative iron correlate to oil consumption or the viscosity grades tested?*
 - 1.3.1.5.3. This analysis could help "lock down" the parts of the procedure that impact hardware longevity.

1.3.2. Update from Southwest:

- 1.3.2.1. They conducted some trials with the external blowby system shortly after the Precision Matrix.

1.3.3. Update from Lubrizol:

- 1.3.3.1. Their stand has been committed to internal testing over the last month.
- 1.3.3.2. Lubrizol would eventually like to perform some trials with the external blowby system and one-way check valve.

1.3.4. Update from Afton:

- 1.3.4.1. Their stand has recently been devoted to internal testing.
- 1.3.4.2. They eventually want to focus on "gray" areas of the procedure (i.e. cylinder head changes, new cylinder head break-in, etc.).

1.4. Engine Management:

1.4.1. Comments from Afton:

- 1.4.1.1. Afton would like this sub-group to discuss engine management.

- 1.4.1.2. This includes discussing whether an engine-based LTMS system should be used.
- 1.4.1.3. There is a lot of candidate data being generated on engines that have never run a reference oil.
 - 1.4.1.3.1. *Can this data still be used if the Surveillance Panel switches to an engine-based LTMS system?*
- 1.4.1.4. This group also needs to establish alignment on how to handle camshaft lobe failures.

1.4.2. Comments from Intertek:

- 1.4.2.1. They feel strongly that there will not be an engine-based LTMS system.
- 1.4.2.2. The procedure needs strict rules regarding engine "health".
 - 1.4.2.2.1. Excessive engine wear can impact test severity.
- 1.4.2.3. This group needs to define a camshaft lobe failure.
 - 1.4.2.3.1. Intertek has reconditioned several camshaft lobe failure engines since the Precision Matrix.
 - 1.4.2.3.2. They use a rebuild procedure that was agreed upon by the Surveillance Panel but has not yet been documented.
- 1.4.2.4. Cumulative Iron Limit:
 - 1.4.2.4.1. *Should this group recommend placing a cumulative iron limit on engine life?*
 - 1.4.2.4.2. They recommend two separate cumulative iron limits:
 - 1.4.2.4.2.1. Maximum iron accumulated over the engine's life.
 - 1.4.2.4.2.2. Maximum end-of-test iron for a single test.
 - 1.4.2.4.3. An engine would be deemed unusable if it exceeds either of these limits.

1.4.3. Comments from Lubrizol:

- 1.4.3.1. It is premature to dismiss the possibility of an engine-based LTMS system.
- 1.4.3.2. Lubrizol agrees with Afton's suggestion that this sub-group should initially focus on engine management and camshaft lobe failures.

1.4.4. Comments from Toyota:

- 1.4.4.1. A correlation between engine hours and test severity can occur.
- 1.4.4.2. The important question to ask is, "why is this engine hour effect occurring?".
- 1.4.4.3. This group needs to investigate all likely causes.
 - 1.4.4.3.1. For example, excessive bore wear can lead to high oil consumption.
 - 1.4.4.3.2. High oil consumption can, in turn, result in accelerated oil degradation.
- 1.4.4.4. Monitoring cumulative iron levels may be useful.
 - 1.4.4.4.1. This parameter can be used to predict when issues like excessive bore wear can impact oil consumption.

1.5. Upcoming Reference Tests:

- 1.5.1. The calibration period for most of the Sequence IVB stands is ending soon.
- 1.5.2. *Should the labs calibrate with engines that have a high number of hours on them?*
 - 1.5.2.1. Southwest, Lubrizol and Intertek all offered to use older engines for their calibration tests in June.
- 1.5.3. This group will also need to discuss the upcoming BOI/VGRA matrix.
 - 1.5.3.1. Stands that will be included in BOI/VGRA testing will need to be calibrated before the matrix starts.

1.6. Cylinder Head Changes:

1.6.1. Comments from Toyota:

- 1.6.1.1. Cylinder head changes were originally introduced to address valve seat wear and tappet bore wear.
- 1.6.1.2. A cylinder head change also provides an opportunity to inspect cylinder bores.

- 1.6.1.3. One option is to perform cylinder head changes after 4-runs, and then run the engine block for a total of 8-runs.

1.6.2. Comments from Intertek:

- 1.6.2.1. Intertek did something similar a few months ago.
- 1.6.2.2. That engine had to be decommissioned during its 7th run.
 - 1.6.2.2.1. The engine suffered a camshaft lobe failure at 145HRS.
- 1.6.2.3. Intertek has started the practice of bore scoping engines between tests that used poor performing oils.

1.7. Afton's Calibration Status:

- 1.7.1. Buscher believes that Afton's two prove-out tests will be sufficient to calibrate their stand.
- 1.7.2. This calibration will extend through August.

1.8. External Blowby System:

1.8.1. Comments from Toyota:

- 1.8.1.1. The purpose of the external blowby system is to improve blowby control.
- 1.8.1.2. During the DOE matrix, there was minimal lab-to-lab variation.
- 1.8.1.3. However, recent testing has shown that there is more lab-to-lab variation.
 - 1.8.1.3.1. They are questioning whether the external blowby system is playing a role in this.
- 1.8.1.4. A previous report published by Chevron (*Gasoline-Engine Camshaft Wear: The Culprit is Blow-By*) found a correlation between NO_x level, oil degradation and sludge formation.
 - 1.8.1.4.1. *Is a similar situation happening with the IVB test?*
 - 1.8.1.4.2. If so, NO_x could be the source of the variation between laboratories.
- 1.8.1.5. Intertek agreed that this group should focus on blowby gas and the blowby system.

1.8.2. Comments from Intertek:

- 1.8.2.1. Precision during the Precision Matrix was not as good as it was during the DOE Matrix.
- 1.8.2.2. Most of the changes made to the test between these two matrices improved repeatability.
- 1.8.2.3. The corrosive aspect of this test is probably more severe now than during the DOE Matrix.
- 1.8.2.4. They would like to revisit two changes to the procedure that were made somewhat recently:
 - 1.8.2.4.1. Controlling exhaust backpressure during all stages instead of just during Stage 2.
 - 1.8.2.4.2. Coolant flow direction through the engine.

1.8.3. NOX Level on IAR165:

- 1.8.3.1. Intertek has been monitoring NO_x on IAR165.
- 1.8.3.2. NO_x appears to peak during the transition.
- 1.8.3.3. NO_x also appears to climb as the test progresses.
 - 1.8.3.3.1. It is currently above 4000ppm.

1.9. Format for Sub-Group Meetings Moving Forward:

- 1.9.1. Lubrizol sent out a complete action item list prior to this conference call.
 - 1.9.1.1. Intertek will update this list with action items from their notes.
- 1.9.2. Lubrizol proposed having Intertek send out an agenda a day before each meeting.
- 1.9.3. Lubrizol will send out an updated action item list and minutes from the previous week's meeting.

- 1.9.4. Lubrizol recommended that this sub-group should try to address 3-5 action items each week.
- 1.9.5. During next week's meeting, Buscher will focus exclusively on this action item list so that this sub-group can develop a strategy to move forward.

1.10. Oil Charge:

- 1.10.1. Southwest would like this sub-group to consider going back to the original initial oil charge for this test.
 - 1.10.1.1. The new, larger oil charge may no longer be needed because of the redesigned oil pan.
- 1.10.2. *Are people willing to risk problems related to aeration?*

2. TEST PROCEDURE SUB-GROUP:

2.1. Opening Comments from Southwest:

- 2.1.1. They plan to use Lubrizol's action item list to drive the agendas for this sub-group.
- 2.1.2. This sub-group needs to review Section 4 of the procedure.
 - 2.1.2.1. Section 4 contains the rebuild instructions for engines that have experienced a camshaft lobe failure.
 - 2.1.2.2. This is the most important action item for this sub-group.

2.2. Cylinder Head Changes:

2.2.1. Comments from Affon:

- 2.2.1.1. They want cylinder head changes to be an urgent action item for this sub-group as well.
- 2.2.1.2. Cylinder head swaps are not clearly explained in the procedure.
- 2.2.1.3. *When will they be done?*
- 2.2.1.4. *What hardware should be used?*
- 2.2.1.5. *How will silicone be mitigated?*
- 2.2.2. Intertek noted that the cylinder head rebuild kit does include all the accessory hardware that is needed.
- 2.2.3. Lubrizol cautioned against mixing the test-specific intake valve springs with the "pointy" stock intake camshafts.

2.3. Extended Periods of Downtime:

- 2.3.1. Lubrizol considers extended downtime to be more than 4-hours.

2.3.2. Comments from Intertek:

- 2.3.2.1. Intertek can accept Lubrizol's definition for extended downtime.
- 2.3.2.2. They remove the rocker arm cover and pour drain oil over the lifters and camshafts.
- 2.3.2.3. They place a stock cover over the engine until they are ready to start it back up.

2.3.3. Comments from Southwest:

- 2.3.3.1. Section 11.3.4.1 of the procedure deals with downtime periods over 30-minutes.
- 2.3.3.2. They can modify this section to increase the duration of downtime.

2.3.4. Comments from Affon:

- 2.3.4.1. This section of the procedure should not use the word "permissible".
- 2.3.4.2. The wording needs to clearly state that these instructions must be followed.

2.4. Permissible Data File Length:

2.4.1. Comments from Affon:

- 2.4.1.1. The data acquisition requirements for this test are unusual and hardware intensive.
- 2.4.1.2. The lengths of the data sets posted in the TMC database are all different.
- 2.4.1.3. *How many data points can be missing before a data set is deemed invalid?*

2.4.2. Comments from TMC:

- 2.4.2.1. There are guidelines in the DACA-II document that deal with missing data.
- 2.4.2.2. In general, files cannot be missing more than 1% of their required length.
 - 2.4.2.2.1. That is 7200 data points in the case of the IVB test.

2.5. OHT Update:

- 2.5.1. OHT would like each lab to send them information on the material and dimensions of the timing chain wedges currently in use.
- 2.5.2. The clutch alignment tool will be available soon.

Action Items	Person responsible	Completion Date

Follow-up Notes/Updates	Initials	Date Added

Attendees	Organization	Contact Information