



INTERNATIONAL
Standards Worldwide

Address 100 Barr Harbor Drive
PO Box C700
W. Conshohocken, PA
19428-2959 | USA

Phone 610.832.9500
Fax 610.832.9666
Web www.astm.org

Committee D02 on PETROLEUM PRODUCTS AND LUBRICANTS

Chairman: KENNETH O. HENDERSON, Cannon Instrument Co., 2139 High Tech Road, State College, PA 16803,
(814) 353-8000, Fax: (814) 353-8007, e-mail: kenohenderson@worldnet.att.net
First Vice-Chairman: BEN R. BONAZZA, 3457 WOODVALLEY DRIVE, LAPEER, MI 48446 (810) 664-6769
e-mail: bbonazza@charter.net
Second Vice-Chairman: JANET L. LANE, ExxonMobil Research & Engrg., 600 Billingsport Rd, Paulsboro, NJ 08066-0480
(856) 224-3302, Fax: (856) 224-3616, e-mail: janet.l.lane@exxonmobil.com
First Secretary: RALPH A. CHERRILLO, Shell Global Solutions (US) Inc., Westhollow Tech Cir., 3333 Highway 6 South,
Houston, TX 77082 (281) 544-8789, Fax: (281) 544-8150, e-mail: ralph.cherrillo@shell.com
Second Secretary MICHAEL A. COLLIER, Petroleum Analyzer Co. LP, PO Box 206, Wilmington, IL 60481, (815) 458-0216,
Fax: (815) 458-0217, e-mail: Michael.collier@pacip.com
Staff Manager: DAVID R. BRADLEY, (610) 832-9681, Fax: (610) 832-9668, e-mail: dbradley@astm.org

April 30, 2008

Reply to:

Donald T. Bartlett
The Lubrizol Corporation
29400 Lakeland Blvd.
Wickliffe, OH 44092
(440) 347-2388
(440) 347-2878 (FAX)

ASTM D02.B0.03 L-37 Surveillance Panel

Members and Guests:

Attached for your review and comment are the unconfirmed minutes of the:

- **February 13, 2008 L-37 Surveillance Panel Meeting conducted at the PRI Headquarters, Apollo Room, Warrendale, PA.**

Please direct any corrections or comments to my attention.

Sincerely,

Donald T. Bartlett, Chairman

L-37 Surveillance Panel

Attachments

Report of Meeting
L-37 Surveillance Panel
Warrendale, PA
PRI Apollo Room
February 13, 2008

Sign-in/Review of Agenda & Membership: The meeting was called to order at 08:10 a.m. The sign-in sheet is included as ***Attachment # 1***. Mr. Fett and Mr. Guzikowski joined via teleconference.

The membership list was reviewed by Mr. Bartlett. All members were recently contacted to confirm any membership changes. All members on the voting list have requested to remain members and maintain their voting rights. See ***Attachment # 2***.

A review of the Agenda was performed with no changes. ***Attachment # 3*** represents a PowerPoint presentation the chairman used for the meeting.

Approval of Minutes The minutes of the November 7th Panel meeting were reviewed.

Motion # 1 ⇒ Mr. Koglin, Second ⇒ Mr. Schenkenberger – Approve the November 7, 2007 Surveillance Panel meeting minutes as written. The motion passed unanimously.

Summary of Meeting Discussions

TMC 127 Reference Oil Replacement - Mr. Lind

Attachment # 4 details the L-37 test results on TMC 127 replacement oil. An oil supplier has provided an 11-test matrix for the replacement oil. These 11 tests were performed at 2 labs, on 4 hardware types, on all 4 types of tests. All tests failed on various parameters ranging from failing on ridging (6) to broken tooth or vibration shutdown. The current TMC 127 oil is down to approximately 10 gallons in the industry and will no longer be available. The replacement oil will be known as TMC 134 and will be the fail oil.

Mr. Lind stated that he is comfortable with the data supplied by the supplier and feels the fluid is comparable to the 134. The question is, how do we implement it? Philosophically, the panel did not want to conduct anymore testing with the current hardware. Mr. Lind offered that we can wait to implement by running a few extra side-by-side comparisons between TMC 127 and TMC 134 with the upcoming non-lubrited and lubrited hardware batches. There is a 5 to 10 year supply of TMC 134 oil now at the TMC. The consensus of the panel was to accept the TMC's recommendation to wait to implement during the hardware matrix approvals. The chairman offered that no acceptance bands would be issued as the fluid will only be used as a discrimination oil.

2008 Plain, Lubrited & Retrofit Hardware Update - Please refer to **Attachment #3** and slides 4 through 11 for further details on this subtopic:

Mr. Bartlett provided an overview of panel and Hardware TF activity for the last 6 months.

Mr. Miller provided background information to the reason for needing to rework the most recent (P4L816/B6L566) Lubrited process. The low case hardening and shallow case depth on the 1st round of pinions was the real issue. One of the optional steel materials allowed on the drawings was softer. Therefore the heat treatment was elevated with a change in the micro geometry that negatively affected the drive side pattern. The changes made to the pinions due to metallurgical differences caused the pinions to change shape, so new (second set) of rings were made due to timing and available at the time to match the pinions. The new lubrited axles will use a "new" alternate lubriting process. The new process will be outsourced from Dana in the Ft. Wayne area with much tighter controls on the crystal etch size and volume. The retrofit lubrited axles will also use the alternate lubriting process. It was determined that the 'initial' rings (set aside) from the 2005 non-lubrited batch/heat of steel will be used for the new non-lubrited hardware because Dana believes that they are produced to the print and technically suitable for the L-37 test. The panel agreed.

The chairman provided an overview of the number of axles ordered across the three batches. See slide # 6.

Mr. Gropp asked about timing for the orders. Rings will be at Ft Wayne in the 1st part of March. It will likely take until the end of April to begin builds. Since we approved the use of the 'initial' 2005 non-lubrited rings earlier, an additional order of plain axles is going to be ordered. See Slides 5 & 6. Action item is for labs to update purchase orders to include the desired plain inventory and sent to Dana/Mr. Ojanen.

There was much discussion and a series of motions were made:

Motion # 2 ⇒ Mr. Gropp/Mr. Lind – **Non-lubrited axle hardware approval Matrix** (There are only 3 labs that are participating). Conduct non-lubrited hardware matrix as approved last October with the following exception: Conduct only 3 Standard tests (1 each at Afton, Lubrizol, and SwRI) on TMC 127. Conduct 4 Standard tests on TMC 134. Mr. Gropp volunteered Lubrizol to conduct 2 of the TMC 134 runs. The other tests will be one each at SwRI and Afton. The Motion carried with a vote of 5 for, 0 opposed, and two abstentions. Note: refer to the hand note changes for slide 7.

Mr. Gropp elaborated that the industry should run the TMC 127 first, and run the TMC 134 runs later in the mix.

Motion # 3 ⇒ Mr. Gropp/Mr. Lind – **Retrofit Lubrited axle hardware approval Matrix** (there are 4 labs that are participating). For the lubrited hardware matrix, run as planned from October with the exception of adding 4 TMC 134's for Standard L-37 test.

Mr. Koehler expressed some concerns about whether the additional tests on TMC134 are needed for the lubrited hardware. He feels we will demonstrate the comparison sufficiently in the non-lubrited matrix. Mr. Lind shared that data will show that TMC 127 performs differently on lubrited hardware than non-lubrited hardware and expressed concern over not looking at the new hardware which is expected to perform differently than previous batches.

Mr. Gropp asked how we are going to use TMC 127 or TMC 134 for the future. Mr. Bartlett reminded the panel that the decision was to use only 127 for bringing in a new batch order and not setting bands with LTMS. Many issues contributed to this decision including the fact that we were running low on the failing fluid.

Action Item: Determine when to run 134 on the new and retrofit lubrified hardware.

The motion failed with a vote of 1 for, 3 opposed, and 2 abstentions. Refer to slide 8, matrix stays unmodified.

Motion # 4 ⇒ Mr. Gropp/Mr. Lind - **New Lubrified axle hardware approval Matrix** (there are 2 labs that are participating). Conduct matrix as approved last October with the following exception: Each lab run 1 additional test on the TMC 134 reference fluid. The motion passed with a vote of 2 for, 1 opposed, and 4 abstentions. Refer to slide 9, matrix stays unmodified. The panel expressed comments at earlier meetings that since the hardware are being built at the same time; similar performance is expected with this batch.

Action Item: See Slides # 10 and 11. Hardware TF visits are in place.

Transition to L-37-1 - Mr. Miller – See Attachment # 5

Dana recommends that the hardware be updated as they will no longer support production of the current hardware after this year. Dana will provide several axles to review and develop new test conditions to meet the J2360 stressed conditions. Electric motor upgrade has also been proposed by SWRI to improve test control & adaptability.

The proposed axle design is a current production style axle. This matches what is currently being used in the field. The gear uses the more modern manufacturing method of 3 axis (face hobbing). The ratio of the proposed axle is 4.11:1 which is reduced from the old 5.86:1. The new axle is used in the Ford Econoline van model line.

There are dimensional differences between the current axle and the proposed. The new axle is metric in design. The new axle is a wider axle with wider spring pad mounts. The spring pad mounts are welded at an angle relative to the output plane. The axle tubes are also larger. The new mounting flange could be replaced with a yolk, the spline size is the same, and the current yolk may be able to be used. The axle shafts are held in by c-clips inside the differential, which differs from the current design.

Mr. Schenkenberger expressed concern over the wider spring pads and the pinion nose flex. Mr. Miller remarked that the larger tube diameter may improve this, but cannot confirm at this point.

Mr. Koglin expressed concern over the additional width relative to the L-42 as some labs use 1 rig for both. This could create issues as the current L-37 and L-42 pads share similar mounting widths.

Action Item – Mr. Miller to provide the proposed axle fill volume, & bolt pattern on the axle shaft.

The loading design consideration is higher for the new axle mainly due to the ratio. The initial look was with keeping the test length the same, the contact stress and number of mesh cycles the same. However, this gives us a high bending stress on the tooth and high pinion bearing stress. The torque must be increased by ~ 42% to arrive at the same contact pressure on the tooth.

Mr. Koglin expressed concern over the limitation on the dynamometer curve and torque capacity at the slow speeds.

One option is to develop a new 3-axis face hobbed gear set at the current ratio of 5.86:1. This would reduce the stresses and make it a non-issue.

Dana believes that using miners rule and other predictions, the stress can be elevated to create gear distress without operating in a stress region that destroys teeth or pinion bearings. This sums to running at lower loads at longer periods of time to achieve the same result.

Mr. Koehler raised the question of "Do we want to stay with the model 60 type axle?" We are leading ourselves to using a bigger axle, more energy in the axle and may be oversized for the goals of the test. Or should we step down in size, rather than up in size?

Mr. Fett picked the new axle as the highest ratio model 60 available.

The panel agrees that a smaller axle may be more appropriate for reduced test cost, more ratio availability, and easier test conditions to run. Mr. Miller commented that new model 44 production axle type may also be the wider track / wider mounting pads.

Action Item – Mr. Miller will look at the model 44-axle size with the same goal to evaluate if the smaller axle is appropriate.

Mr. Gropp expressed concern over OEM / LRI opposition to an axle model change if the current design has close ties to light and heavy-duty axles in the field.

Attachment # 6 is a presentation provided by Mr. Koehler. We did not have time for review.

Review January 2008 Gear Calibration Work Shop - Mr. Lind – See Attachment # 7 for pinion data and Attachment # 8 for ring data.

Mr. Lind presented the Rater Calibration data from the January workshop. He challenged the panels & specifically the labs to reduce their rater variability. The current effort of reducing the industry variability has not worked, so Mr. Lind feels that the individual lab engineers and management needs to step up.

Mr. Lind will be bringing the raters charts to lab visits and will be sharing them with the labs. This is a new directive from Mr. Lind and Mr. Farber. The labs don't have a problem with this, and look forward to working with Mr. Lind to help address this issue.

Mr. Gropp expressed concern over the current system, if it should be changed to reflect outliers at the workshops to affect a rater's calibration in the system.

Mr. Koglin raised the concern that some of the outliers may not be due to a specific rater's ability but due to a difficult pinion.

Mr. Lind commented that even though several pinions / rings look poorly, compared with the introduction of RCMS and the workshops, the data has improved. Mr. Lind forces outliers at the workshops to be defended by the raters. He feels that this has improved variation.

These following are examples of the ratings. **Mr. Lind** is concerned with several of the gears and the ratings he sees.

Review of Pinions:

- o Set 1C – Mr. Lind feels that a 7.0 ridging is an outlier.

Review of Rings:

The rings have no targets; however variation is noted in red.

- o Set 1C – Ridging, Ripple and Wear all are variable. Mr. Lind is concerned with a 6.0 to 10.0 rating.

Gear Teeth Chipping Definition - Chairman Bartlett

A previous action item was to address rating issues with two of the RCMS pinion 44 and 45 (pulled the RCMS at a previous meeting). Some raters were formally calling the anomalies at the top land as chipping and others as pitting or broken teeth. Mr. Fett believes this is chipping and is caused from excessive compressive stress built into the gear from the shot peening process.

The chairs request of the panel is to come to a conclusion about a definition. Mr. Smith feels that a definition should be defined and the pinions placed back in active service. The panel discussed possible rating definitions to address the chipping vs. pitting. The general consensus is that it should be considered chipping, and not rated as pitting. The chair suggests a TF recommend a wording / rating aid to address this issue by the April SP meeting.

A motion made by Mr. Smith "Define chipping and put the RCMS pinions 44 and 45 back into use died because of no second.

The panel struggled over building a definition. Mr. Gropp said that the definition will not work if we do not pin down a defined location. Mr. Lind said that we could possibly use something such as "If pitting spreads into the crown of the tooth." The chairman pulled the issue off the table and will bring it forward at a later date due to time constraints.

Motion # 5 ⇒ Mr. Smith, second ⇒ Mr. Koglin. Move to adjourn the meeting at 11:08. Motion passed unanimously.

Respectfully submitted,



Donald T. Bartlett
L-37 Surveillance Panel Chairman

ASTM L-37 Surveillance Panel Membership/Mailing List

Meeting Date: February 13, 2008

Initials*	Name	Voting Status	Company Name & Address	Phone/Email Info
	Agusti, Rachel	Non Voting	AMSTA-TR-D/210 Tank Automotive & Armament 6501 East 11 Mile road Warren, MI 48397-5000	Phone: 586-574-4222 Fax: 586-574-4244 E-Mail: rachel.agusti@us.army.mil
	Barker, Chris	Non Voting	Southwest Research Institute PO Drawer 28510 San Antonio, Texas 78228-0510	Phone: 210-522-2106 Fax: 210-684-7523 E-Mail: chris.barker@swri.org
JTB	Bartlett, Don	Voting/Chair	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347-2388 Fax: 440-347-2878 E-Mail: donald.bartlett@lubrizol.com
DBB	Bell, Don	Non Voting	Afton Chemical 500 Spring Street Richmond, VA 23219	Phone: 804-788-6332 Fax: 804-788-6243 E-Mail: don.bell@aftonchemical.com
	Bryson, Tom	Voting	Mack Trucks 13302 Pennsylvania Avenue Hagerstown, Maryland 21740	Phone: 301-790-6744 Fax: 301-790-5605 E-Mail: thomas.bryson@volvo.com
	Buitrago, Juan	Voting	Chevron Orionite Company 100 Chevron Way Richmond, California 94802	Phone: 510-242-1161 Fax: 510-242-3392 E-Mail: jabu@chevrontexaco.com
	Chambers, Harold	Non-Voting	Ford Motor Co. 110 Livonia 36200 Plymouth, box # 21 Livonia, MI 48150	Phone: 313-805-8591 Fax: 313 35500 Plymouth E-Mail: hchamber@ford.com
	Comfort, Allen	Voting	AMSTA-TR-D/210 Tank Automotive & Armament 6501 East 11 Mile road Warren, MI 48397-5000	Phone: 586-574-4225 Fax: 586-574-4244 E-Mail: allen.s.comfort@us.army.mil
JTB	Dhare, John	Voting	American Axle & Manufacturing 2965 Technology Drive Rochester Hills, MI 48309-3589	Phone: 248-299-6478 Fax: 248-293-6945 E-Mail: Dharej@aam.com
	Eliot, Stephen	Non Voting	ExxonMobil Lubricants & Specialties Leesburg, Virginia	Phone: 703-669-9916 Fax: 703-669-9917 E-Mail: stephen.w.elliott@exxonmobil.com

* Initial to indicate attendance at subject meeting

ASTM L-37 Surveillance Panel Membership/Mailing List

Meeting Date: February 13, 2008

Initials*	Name	Voting Status	Company Name & Address	Phone/Email Info
	Farber, Frank	Non Voting	ASTM Test Monitoring Center 6555 Penn Avenue Pittsburgh, Pennsylvania 15206	Phone: 412-365-1030 Fax: 412-365-1047 E-Mail: fmf@astm.mc.cmu.edu
	Foeking, Brian	Non Voting	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347-2130 Fax: 440-347-9011 E-Mail: brian.foeking@lubrizol.com
	Graziano, Rick	Non-Voting	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347-2058 Fax: 440-347-2878 E-Mail: rick.graziano@lubrizol.com
	Green, Galen	Non-Voting	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347- Fax: 440-347- E-Mail: galen.green@lubrizol.com
	Gropp, Jerry	Non Voting	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347-1223 Fax: 440-347-1555 E-Mail: jerrold.gropp@lubrizol.com
MB	Haire, Mike	Non Voting	Chevron Oronite Company 100 Chevron Way, Rm 71-7302 Richmond, California 94802	Phone: 510-242-2740 Fax: 510-242-3758 E-Mail: mhaire@chevron.com
SM	Higuchi, Sam	Non Voting	Afton Chemical 500 Spring Street Richmond, VA 23218 23219	Phone: 804-788-5375 Fax: 804-788-6358 E-Mail: samuel.higuchi@attonchemical.com
	Huron, John	Non Voting	Chevron Oronite Company LLC Suite 210 San Antonio, Texas 78228-1374	Phone: 210-731-5609 Fax: 210 731 5699 E-Mail: huro@chevronlexaco.com
	Kanga, Percy	Non Voting	ExxonMobil Research & Engineering 600 Billingsport Road Paulsboro, New Jersey 08066	Phone: 856-224-2094 Fax: 856-224-3613 E-Mail: percy.r.kanga@exxonmobil.com
	Koehler, Brian	Voting	Southwest Research Institute PO Drawer 28510 San Antonio, Texas 78228-0510	Phone: 210-522-3588 Fax: 210-684-7523 E-Mail: bkoehler@swri.org
K.C.	Koglin, Cory	Voting	Afton Chemical 500 Spring Street Richmond, VA 23218 23219	Phone: 804-788-5305 Fax: 804-788-6358 E-Mail: CoryKoglin@attonchemical.com

* Initial to indicate attendance at subject meeting

ASTM L-37 Surveillance Panel Membership/Mailing List

Meeting Date: February 13, 2008

Initials*	Name	Voting Status	Company Name & Address	Phone/Email Info
	Kozlowski, Ralph	Non Voting	PARC Technical Services, Inc. 100 William Pitt Way Pittsburg, PA 15238	Phone: 412-826-5044 Fax: 412-826-5443 E-Mail:
<i>DL</i>	Lind, Don	Voting	ASTM Test Monitoring Center 655 Penn Avenue Pittsburgh, Pennsylvania 15206	Phone: 412-365-1034 Fax: 412-365-1047 E-Mail: dml@astmnc.cmu.edu
	Linden, Jim	Voting	GM Research & Development 30500 Mound Rd. MC 480-106-160 Warren, MI 48090	Phone: 586-986-1888 Fax: 586-986-2094 E-Mail: James.L.Linden@GM.com
	Lochte, Michael	Non Voting	Southwest Research Institute PO Drawer 28510 San Antonio, Texas 78228-0510	Phone: 210-522-5430 Fax: 210-684-7523 E-Mail: Mlochte@swri.org
	Marougy, Thelma	Voting	Eaton Corporation 26201 Northwestern Highway Southfield, MI 48034	Phone: 248-226-6985 Fax: 248-226-2739 E-Mail: thelmaemarougy@eaton.com
<i>DNA</i>	Martin, Dan	Non Voting	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347-4400 Fax: 440-347-2878 E-Mail: danmartin@lubrizol.com
	McGione, Bruce	Voting	Mertor Automotive 2135 West Maple Troy, Michigan 48084	Phone: 248-435-9929 Fax: 248-435-1411 E-Mail: Bruce.McGione@ArvinMertor.com
<i>KM</i>	Miller, Kenny	Voting	Dana Corporation 1293 Glenway Drive Statesville, NC 28677	Phone: 704-878-5762 Fax: 704-878-5735 E-Mail: Kenny.miller@dana.com
	Podboy, Allison	Non Voting	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347-4679 Fax: 440-347-4400 E-Mail: alpd@lubrizol.com
	Pole, Jami	Non Voting	American Axle & Manufacturing 2965 Technology Drive Rochester Hills, MI 48309-3589	Phone: 248-299-6598 Fax: 248-299-6598 E-Mail: jami.pole@aam.com
<i>CP</i>	Pengaman, Chris	Non Voting	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347-4225 Fax: 440-347-2878 E-Mail: chris.pengaman@lubrizol.com

* Initial to indicate attendance at subject meeting

Attachment 1

Page 3 of 4

Reference 2/13/08

ASTM L-37 Surveillance Panel Membership/Mailing List

Meeting Date: February 13, 2008


Initials*	Name	Voting Status	Company Name & Address	Phone/Email Info
	Purnell, Keith	Non Voting	Performance Review Institute 161 Thornhill Rd. Warrendale, Pa. 15086-7527	Phone: 724-772-1616 ext 8182 Fax: 724-772-1699 E-Mail: kpurnell@sae.org
	Radonich, Peter	Non Voting	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347-2184 Fax: 440-347-9011 E-Mail: peter.radonich@lubrizol.com
	Salvatore, Rea	Voting	Infinium USA, L.P. 1900 E. Linden Ave Linden, NJ 08066 78228-0510	Phone: 908-474-6602 Fax: 908-474-3597 E-Mail: salvatore.rea@infinium.com
	Sanchez, Art	Non Voting	Southeast Research Institute PO Drawer 28510 San Antonio, Texas 78228-0510	Phone: 210-522-3445 Fax: 210-680-1777 E-Mail: asanchez@swri.org
CS	Schenkenberger, Chris	Non Voting	The Lubrizol Corporation 29400 Lakeland Boulevard Wickliffe, Ohio 44092	Phone: 440-347-2927 Fax: 440-347-2878 E-Mail: chris.schenkenberger@lubrizol.com
	Smith, Dale	Voting	Interek - PARC Technical Services, Inc. 100 William Pitt Way Pittsburgh, PA 15238	Phone: 412-423-1120, ext 403 Fax: 412-826-5443 E-Mail: Dale.Smith@interek.com
	Sullivan, Bill	Non Voting	William T. Sullivan, Inc. 5 Scheiber Drive Brick, NJ 08723	Phone: 908-930-3512 Fax: 267-220-7750 E-Mail: wsullivan@comcast.net
	Vetel, Paula	Voting	D. A. Stuart Company 4580 Weaver Parkway Warrenville, Illinois 60555	Phone: 630-393-8859 Fax: 630-393-8577 E-Mail: pvetel@dasuart.net
	Zakaran, Jack	Non Voting	Chevron Products 100 Chevron Way Richmond, CA 94802	Phone: 510-242-3595 Fax: 510-242-3758 E-Mail: jaza@chevron.com

* Initial to indicate attendance at subject meeting

Attachment
Page 4 of 4
Reference 2/13/08

L-37 Surveillance Panel Voting Members

Donald Bartlett	The Lubrizol Corporation (Chairman)
Tom Bryson	Volvo Powertrain Corporation
Juan Buitrago	Chevron Oronite Company
Allen Comfort	AMSTA-TR-D/210 US Army Tacom-Tardec
John Dharte	American Axle & Manufacturing
Brian Koehler	Southwest Research Institute
Cory Koglin	Afton Chemical Company
Don Lind	ASTM Test Monitoring Center
Jim Linden	GMR Research and Development
Thelma Marougy	Eaton Corporation
Bruce McGlone	ArvinMeritor Materials Engineering
Kenny Miller	Dana Corporation
Salvatore Rea	Infineum
Dale Smith	Intertek - PARC Technical Services
Paula Vettel	D.A. Stuart Company



Lubrizol

L-37 Surveillance Panel
 PRI Headquarters,
 Warrendale, Pa.
 February 13, 2008

Donald Bartlett

Lubrizol

L-37 SP Agenda

I. Call to Order, Agenda, & Membership Review	
II. SP Minutes to Approve:	
✓ November 7, 2007 SP Meeting	15 min
III. TMC 127 Reference Oil Replacement	20 min
IV. 2008 Green, Lubrified & Retrofit HDW Update	45 min
V. L-37-1 Development – Miller	20 min
VI. Review January 2008 Gear Calibration WS – Lind	20 min
VII. Pitting/Spalling vs. Chipping RCMS Pinions 44 and 45	20 min
VIII. New Business	
IX. Adjournment	

2

Lubrizol

L-37 Surveillance Panel Voting Members

Donald Bartlett	The Lubrizol Corporation (Chairman)
Tom Bryson	Volvo Power Train Corporation
Juan Buitrago	Chevron Oronite Company
Allen Comfort	AMSTA-TR-DZ10 US Army Tacom-Tardec
John Dharte	American Axle & Manufacturing
Brian Koehler	Southwest Research Institute
Cory Koglin	Aflon Chemical Company
Kenny Miller	Dana Corporation
Don Lind	ASTM Test Monitoring Center
Jim Linden	GMR Research and Development
Thelma Marougy	Eaton Corporation
Bruce McGlone	ArvinMeritor Materials Engineering
Salvatore Rea	Infinium
Dale Smith	PARC Technical Services
Paula Vettel	D.A. Stuart Company
Total 15 Voting Members	

3

Attendance 3
 Date 1/26/7
 Reference 2/13/08

Lubrizol

TMC 127 Ref Oil Replacement

- ❖ TMC 127 is used only as a discrimination oil – Fall
- ❖ Replacement oil will be TMC 134 – Fall oil - discrimination
- ❖ Review data – Lind
- ❖ How do we implement TMC 134 ?
- ❖ Do we run TMC 134 in the hardware approval matrix ?

Lubrizol

2008 Hardware Status to Date

- ✓ Dana statements and agreements with ASTM to date:
 - ✓ Purchased one heat steel for all non-lubricated and lubricated pinions.
 - ✓ Purchased one heat steel for all lubricated rings.
 - ✓ Non-lubricated rings will use rings from the 2005 batch/heat of steel.
 - ✓ Will "same batch lot" order all associated parts for new axle assembly builds.
- ✓ Green - new axle assembly cost is \$ 992.00
- ✓ Lubricated - Retrofit of 2007 B8L566 and 'other' parts
 - ✓ At no cost to labs
 - ✓ Labs to pay shipping one way
 - ✓ Axles to use the "Alternate" lubricating process
- ✓ Lubricated - new axles assembly cost is \$ 1005.00
 - ✓ Axles to use the "Alternate" lubricating process

Lubrizol

2008 Hardware Order Information

Axle Type	Total Order	Ring Code	Pinion Code	Labs
Plain	898	P4T813	New - y	3
Lub - Retrofit	975	New - x	New - y	4
Lub - New	234	New - x	New - y	2
Total	2107			

Additional order of Plain Axles

Afton - 40-50
 Lubrizol - 80-98
 SwRI - 40-50

Attachment 3
 Page 2 of 7
 Reference 8/13/08

Lubrizol

Agreement 1 – Oct. 25th 2007 SP Telecom Mtg.

- ✓ Non-Lubrited Hardware Matrix – 3 Labs
- ✓ Conduct the standard 44 - test approval matrix

3

- › 1 Standard test on TMC 127 or 134
- › 8 Standard test on TMC 151
- › 8 Standard test on TMC 152
- › 8 Standard test on TMC 153
- › 8 Canadian test on TMC 152
- › 8 Canadian test on TMC 153

4 STANDARD TMC-134

modified

Lubrizol

Agreement 2 – Oct. 25th 2007 SP Telecom Mtg.

- ✓ Lubrited Retrofit Hardware Matrix – 4 Labs
- ✓ What ever the bulk of the hardware build is (retrofit) or all new lubrited assembly builds), the labs will conduct the standard 44 - test matrix
- › Consensus was the retrofit plus all new axle assemblies would be of the same heat of steel
- › 4 Standard test on TMC 127 or 134
- › 8 Standard test on TMC 151
- › 8 Standard test on TMC 152
- › 8 Standard test on TMC 153
- › 8 Canadian test on TMC 152
- › 8 Canadian test on TMC 153

no TMC 134

NOT Modified

Lubrizol

Agreement 3 – Oct. 25th 2007 SP Telecom Mtg.

- ✓ New Lubrited Hardware Matrix – 2 Labs
- ✓ For the smaller subset of lubrited hardware builds, each lab who orders a portion of this smaller subset will conduct 6 more tests as follows
- ✓ It was further stipulated that: if only one lab orders the smaller subset of hardware, this lab must run the six tests in duplicate
 - › 1 Standard test on TMC 127 or 134
 - › 1 Standard test on TMC 151
 - › 1 Standard test on TMC 152
 - › 1 Standard test on TMC 153
 - › 1 Canadian test on TMC 152
 - › 1 Canadian test on TMC 153

2 STANDARD TMC 134

modified

Attachment 3
 Page 3 of 7
 Reference 2/13/08

Lubrizol

Lab HTF Visit to Maumee Facility

❖ Wednesday, March 5, 2008

- Review and document the lubrited retrofit assembly process
- Tour the area shop performing the retrofit
- Develop plan for return and re-distribution
- Document expectations
- Address other necessary items to insure success

10

Lubrizol

Lab HTF Visit to Ft. Wayne

❖ Thursday, March 6, 2008.

- Ft. Wayne agreed to not cut any material for the three axle batches until after this meeting
- Review the drawings and re-validate any changes required before proceeding.
- Will Focus on the 2005 non-lubrited gear batch success (P4L792N/1L417) and review any changes and any line changes made by Ft. Wayne since that batch
- Review the heat treating process
- Review the alternate lubrited process
- Resolve any issues with contact pattern position i.e. - L1 vs. L2 and L3 (procedure specified)

11


Lubrizol


Discussions - Transition to L-37-1


- ❖ Current steel being used in production today is 5124.
- ❖ Have the newer 3-axis gear design vs. 2-axis design
- ❖ Could be procured with either a 4.10 or 3.73 ratio vs. 5.86
- ❖ Phase 1
 - » Dana to provide a small quantity of current production axes (about a pallet) for matrix testing
 - » Use current engine/transmissions/operating conditions
 - » Labs conduct limited tests on identified reference oils
 - » Evaluate distress

12

Attachment 3
 Page 4 of 7
 Reference 2/15/08


Discussions - Transition to L-37-1
<ul style="list-style-type: none"> ❖ Phase 2 <ul style="list-style-type: none"> » Labs will want to use the current stand configuration for L-37 work since we have ordered approximately 3-4 years worth of sales. » Use current engine/transmission specified in D6121 » Dana and industry to work together on operating conditions and test length to yield SAE J2360 diesel equivalence » More matrix testing to develop a tie to history ❖ Phase 3 <ul style="list-style-type: none"> » Suggestions for electric motor vs. gasoline engine power plant ❖ Dana Presentation - Miller
13


L-37 SP Agenda
<ol style="list-style-type: none"> I. Call to Order, Agenda, & Membership Review II. SP Minutes to Approve: <ul style="list-style-type: none"> ✓ November 7, 2007 SP Meeting III. TMC 127 Reference Oil Replacement 15 min IV. 2008 Green, Lubrified & Retrofit HDW Update 20 min V. L-37-1 Development – Miller 45 min VI. Review January 2008 Gear Calibration WS – Lind 20 min VII. Pitting/Spalling vs. Chipping RCMS Pinions 44 and 45 20 min VIII. New Business IX. Adjournment
14


L-37 SP Agenda
<ol style="list-style-type: none"> I. Call to Order, Agenda, & Membership Review II. SP Minutes to Approve: <ul style="list-style-type: none"> ✓ November 7, 2007 SP Meeting III. TMC 127 Reference Oil Replacement 15 min IV. 2008 Green, Lubrified & Retrofit HDW Update 20 min V. L-37-1 Development – Miller 45 min VI. Review January 2008 Gear Calibration WS – Lind 20 min VII. Pitting/Spalling vs. Chipping RCMS Pinions 44 and 45 20 min VIII. New Business IX. Adjournment
15

Attachment	<u>3</u>
Page	<u>5 of 7</u>
Reference	<u>2/13/08</u>





Lubrizol

Pitting/Spalling vs. Tooth Chipping

- ❖ RCMS Pinions 44 and 45 –
- ❖ Greg Felt comments –
 - Believes that the anomaly at the top of the L37 gear teeth is chipping
 - is a result of the wear on the tooth face and the compressive residual stress from the shot peening operation
 - The shot peening operation puts a considerable amount of compressive residual stress in the corner of the tooth tip
 - Shot peening tends to make it want to crack or pop off
 - When there is wear on the tooth face the stress is relieved on one side only which tends to cause these cracks
 - These are not normal pitting which is associated with localized high contact stresses or poor lubricant performance.

Lubrizol

Attachment 3
 Page 6 of 7
 Reference 2/13/20

Lubrizol
1000 Lakeside Drive, Wickliffe, OH 44092-1099

Pitting/Spalling vs. Tooth Chipping

Panel Direction ?

- Define the contact area around the crown ?
- Write a description for chipping ?
- Excluded and note in comments section ?
- Put pitlons back into RCMS ?

19

Lubrizol
1000 Lakeside Drive, Wickliffe, OH 44092-1099

Thank You !

- 8 Hardware TF Teleconferences Since Nov SP Mig
 - All discussions documented
 - Will be included with Feb SP meeting minutes
- Dana
- TMC
- Labs

20

Attachment	3
Page	2067
Reference	2/13/08

L-37 Test Results on TMC 127 Replacement

Lab	Hardware	Batch	Type	Test Version	Wear	Rippling	Pinion Ratings	Pitting/Spalling	Scoring	Comments
A	V1L351/P4T771		Nonlubrted	Standard	6	7	5	9.9	10	Ring failed Ridging (5)
A	V1L417/P4L792		Nonlubrted	Standard	7	5	8.0		10	Ring failed Ridging (5)
B	V1L417/P4L792		Nonlubrted	Standard	6	8	3.0		10	Ring failed Ridging (4). One broken ring tooth.
A	V1L417/P4L792		Nonlubrted	Canadian	6	4	8	9.9	10	Ring failed Ridging (6)
B	V1L417/P4L792		Nonlubrted	Canadian	6	6	6	9.7	10	Ring failed Ridging (6)
A	L247/T758A		Lubrted	Standard	7	7	4	3.0	10	One broken ring tooth. Ring failed Ridging (5) and Pitting/Spalling (8.0).
B	L247/T758A		Lubrted	Standard	3	9	3	3.0	10	Ring failed Ridging (5). One broken pinion tooth.
A	B6L566/P4LB16		Lubrted	Standard	6	7	7	9.3	10	Ring failed Ridging (7). Chipping on four pinion teeth.
B	B6L566/P4LB16		Lubrted	Standard	-	-	-	-	-	Test terminated at 12 hours due to vibration. One cracked ring tooth.
A	L247/T758A		Lubrted	Canadian	4	8	9	9.3	10	Ring failed Ridging (7). Chipping on five pinion teeth.
A	B6L566/P4LB16		Lubrted	Canadian	-	-	-	-	-	Test terminated at 20 hours due to vibration. Numerous broken pinion and ring teeth.

Attachment
Page
Reference
1541
2/13/00
4

Notes: 1) Falling distress parameters are highlighted

2) The B6L566/P4LB16 batch of lubrted hardware was not approved for use in this test



What is the final Volume?

Off Highway Systems




Kenny Miller, Gear Engineering

L37 Surveillance Panel meeting: Presentation to look at potential new axle for L37 lube test. The data provided compares existing hypoid hardware (L37) with potential new hardware for lube testing (L37-1). The comparison includes dimensional/physical as well as power transmission capacity parameters. Also a overview of test conditions required to provide equivalent results is provided.

February 13, 2008

OHS Product Engineering



Attachment	5
Page	16/5
Reference	2/13/08



Test conditions for L37-1 to acquire equivalent contact pressure and equivalent pinion cycles
 Output speed = 114.3 RPM
 Axle output torque = 5,479 ft-lbs

* L37 values shown are for current test torque and speed [3,480 ft-lbs (both sides) and 80 output RPM]..
 L37-1 conditions are at torque that is matching the contact stress of L37.
 Note: total axle torque (both sides) for current L37 test is 41,800 in-lbs (3,480 ft-lbs).

	Gleason Z-factor/PINION (Hertzian)	Gleason Q-factor/PINION (Lewis parabola)	Gleason Q-factor/GEAR (Lewis parabola)	Contact stress* Sc (lbs/in ²)	Pinion stress* Sp (lbs/in ²)	Gear stress* Sp (lbs/in ²)
L37	4788.19	8.17100	1.58244	404,305	58,313	66,146
L37-1	3192.67	4.76199	1.53040	404,306	76,366	100,624

Comparison of strength/durability factors & stresses, L37 (current) to L37-1 (new)

L37 axle P/N = 060AA100-2
 L37-1 axle P/N = 2004681-5

Attachment 5
 Page 2 of 5
 Reference 2/13/08

February 13, 2008

Reference

* asymmetric hole positioning
 ** pinion up

	1	2	3	4	5	6	7	8	9	10
axle shaft flange (face-to-face)	62.000	55.680	40.056	1.125	.500	U-joint yoke	(6) .385"-.390" holes 4.00 circle	N/A	0°	2.750
axle housing (flange-to-flange)										
spring pads (center-to-center)										
hypoid offset										
pinion center-to-center of spring pads										
pinion flange description										
axle tube flange description										
pinion face-to-center of axle										
carrier-to-spring pad rotation										
axle tube diameter										
	66.470	58.974	48.920	1.125	1.860	Flange type, 8 holes (M12-1.75_4.25" dia.)	(4) .651"-.657" holes* 5.79" circle	12.235	9.28° **	3.500

Comparison of physical dimension, L37 (current) to L37-1 (new)

Unit = inches, Values = nominals


L37 axle P/N = 060AA100-2
 L37-1 axle P/N = 2004681-5

Attachment: 5
 Page: 2/13/08
 Reference: February 13, 2008

Smith-need Root Circle Sing
 8 Root circle

- new axle has C dips
 - Today only lubed
 - needs different sheet beams





February 13, 2008

Attachment 5
Page 4 of 5
Reference 2/13/08

L37 axle P/N = 060AA100-2
L37-1 axle P/N = 2004681-5



THAT'S IT! DISCUSSION / QUESTIONS ?

February 13, 2008

Attachment	5 of 5
Page	2/13/08
Reference	

L-37 S.P. Presentation Next Generation L-37

- By: Brian Koehler; SwRI
- Feb. 13, 2008
- PRI, Warrendale, PA

SwRI Proposes Electric Drive

- SwRI proposes an Electric Motor and variable speed drive for the next generation of L-37 test

Why Now?

- L-37 axles after 2008 will have significantly different gear ratio
- Axle gears will also have different machining process and likely different metal
- Test conditions will have to be changed to adjust for above

Attachment	6
Page	14/3
Reference	2/13/08

Why Electric?

- Better drive durability
- Better drive control precision
- Safer than fueled engine
- Simpler stand design
- Lower energy cost
- Unlimited speed control points within speed range
 - We will use direct drive (no gear box)

Negatives?

- Mainly price:
- One time investment of \$29,000 to \$36,000 for motor and drive.
- Plus price of electrical service and service filtering if needed
- Will have to make slight compromise on max. and min. pinion speed range.
 - Existing L-37 min. and max. speeds require larger motor and drive to be met.
 - Slight compromise could down size power requirements significantly.

Suggestions (in this order)

- Dana to spec. out conditions for new axle
- SwRI will work through a drive and motor supplier to make hardware recommendation
- Labs will meet to discuss min. need.
 - Some may want more capability for other uses.
- Labs to purchase same drive and motor make and model?
- Use reference oils to tie new to old

Attachment
Page
Reference

4
2 of 3
2/13/08

Example

- For existing L-37:
- 460 Volt, 3 phase, 400 amp service needed
- Drive and motor would be in 200 to 250 HP Range
 - With small speed range compromise

Attachment	6
Page	3 of 3
Reference	2/3/29

ASTM Gear Calibration Workshop
Richmond, VA January 15, 16, 17 & 18, 2008

L-37 PINION GEARS

RCMS

SET #	DISTRESS	6	7	10	11	22	25	29	30	MAX	MIN	AVG	Std Dev	Pinion #	Mean
1C	Ridging	6.0	5.0	6.0	7.0	6.0	7.0	5.0	6.0	7.00	5.00	6.00	0.756	1	5.4
1C	Rippling	7.0	6.0	7.0	8.0	6.0	7.0	7.0	7.0	8.00	6.00	6.88	0.641		7.8
1C	Wear	5.0	6.0	6.0	6.0	6.0	6.0	5.0	6.0	6.00	5.00	5.75	0.463		5.9
1C	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	9.90	9.90	0.000		9.91
1C	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	10.00	10.00	0.000		
2C	Ridging	9.0	8.0	9.0	9.0	9.0	9.0	9.0	9.0	9.00	8.00	8.88	0.354	7	9.2
2C	Rippling	9.0	9.0	8.0	10.0	8.0	9.0	10.0	10.0	10.00	8.00	9.13	0.835		8.6
2C	Wear	6.0	6.0	6.0	6.0	7.0	7.0	6.0	8.0	8.00	6.00	6.50	0.756		7.8
2C	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.8	9.90	9.80	9.89	0.035		9.87
2C	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	10.00	10.00	0.000		
3C	Ridging	5.0	5.0	6.0	5.0	7.0	6.0	5.0	5.0	7.00	5.00	5.50	0.756	15	5.6
3C	Rippling	6.0	9.0	9.0	9.0	8.0	9.0	9.0	9.0	9.00	6.00	8.50	1.069		8.6
3C	Wear	5.0	5.0	5.0	5.0	6.0	6.0	5.0	6.0	6.00	5.00	5.38	0.518		5.4
3C	Spitting	7.0	8.0	8.0	8.0	8.0	8.0	8.0	7.0	8.00	7.00	7.75	0.463		7.56
3C	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	10.00	10.00	0.000		
4C	Ridging	8.0	7.0	7.0	8.0	8.0	8.0	8.0	8.0	8.00	7.00	7.75	0.463	25	8.1
4C	Rippling	6.0	7.0	6.0	8.0	7.0	7.0	7.0	7.0	8.00	6.00	6.88	0.641		7.6
4C	Wear	5.0	7.0	6.0	6.0	6.0	6.0	6.0	7.0	7.00	5.00	6.13	0.641		6.7
4C	Spitting	9.8	9.7	9.9	9.9	9.9	9.9	9.9	9.9	9.90	9.70	9.86	0.074		9.9
4C	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	10.00	10.00	0.000		
5	Ridging	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	10.0	9.0	9.50	0.535	26	9.80
5	Rippling	10.0	9.0	10.0	10.0	9.0	9.0	9.0	9.0	10.0	9.0	9.38	0.518		9.30
5	Wear	9.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0	9.0	8.0	8.13	0.354		8.80
5	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000		9.98
5	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
6	Ridging	10.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	10.0	9.0	9.13	0.354	33	9.00
6	Rippling	10.0	9.0	9.0	10.0	9.0	9.0	9.0	9.0	10.0	9.0	9.25	0.463		9.20
6	Wear	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.00	0.000		6.30
6	Spitting	3.0	3.0	2.0	2.0	3.0	2.0	6.0	1.0	6.0	1.0	2.75	1.488		2.33
6	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
7	Ridging	8.0	7.0	7.0	7.0	7.0	7.0	8.0	6.0	8.0	8.0	7.13	0.641	38	7.30
7	Rippling	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.00	0.000		9.20
7	Wear	6.0	7.0	6.0	7.0	7.0	7.0	6.0	6.0	7.0	6.0	6.38	0.518		6.70
7	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000		9.92
7	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
8	Ridging	9.0	8.0	9.0	8.0	8.0	9.0	9.0	9.0	9.0	8.0	8.63	0.518	39	8.70
8	Rippling	9.0	8.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	8.88	0.354		8.50
8	Wear	6.0	6.0	6.0	6.0	7.0	7.0	6.0	6.0	7.0	6.0	6.13	0.354		6.80
8	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000		9.92
8	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		

Attachment 7

Page 147
 Reference 5/1/10

**ASTM Gear Calibration Workshop
Richmond, VA January 15, 16, 17 & 18, 2008**

L-37 PINION GEARS

SET #	DISTRESS	6	7	10	11	22	25	29	30	MAX	MIN	AVG	Std Dev	Pinion #	Pinion Mean
9	Ridging	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.00	0.000	41	9.30
9	Rippling	10.0	10.0	9.0	10.0	9.0	9.0	10.0	9.0	10.0	9.0	9.50	0.535		9.30
9	Wear	7.0	7.0	7.0	8.0	7.0	6.0	8.0	6.0	8.0	8.0	7.00	0.756		6.80
9	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000		9.92
9	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
10	Ridging	9.0	8.0	8.0	8.0	8.0	8.0	9.0	8.0	9.0	8.0	8.25	0.463	42	8.80
10	Rippling	9.0	7.0	7.0	8.0	7.0	6.0	8.0	7.0	9.0	8.0	7.38	0.916		6.80
10	Wear	6.0	6.0	6.0	6.0	7.0	6.0	6.0	6.0	7.0	6.0	6.13	0.354		6.00
10	Spitting	9.9	9.9	9.9	9.9	9.9	9.8	9.9	9.6	9.9	9.6	9.85	0.107		9.80
10	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
11	Ridging	9.0	7.0	8.0	8.0	9.0	8.0	8.0	8.0	9.0	7.0	8.13	0.641	59	New Pinion
11	Rippling	7.0	5.0	6.0	5.0	6.0	5.0	6.0	6.0	6.0	5.0	5.75	0.707		Pinion No
11	Wear	5.0	5.0	5.0	6.0	6.0	6.0	6.0	6.0	6.0	5.0	5.63	0.518		STATS
11	Spitting	9.0	9.0	8.0	8.0	9.0	9.0	9.0	8.0	9.0	8.0	8.50	0.535		
11	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
12	Ridging	9.0	8.0	8.0	9.0	8.0	9.0	10.0	9.0	10.0	8.0	8.75	0.707	55	8.70
12	Rippling	10.0	8.0	9.0	10.0	9.0	9.0	9.0	9.0	10.0	8.0	9.13	0.641		9.20
12	Wear	7.0	7.0	7.0	7.0	7.0	7.0	7.0	6.0	7.0	8.0	6.88	0.354		7.00
12	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000		9.90
12	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
RERATE															
R1/5	Ridging	10.0	10.0	9.0	10.0	9.0	9.0	9.0	10.0	10.0	9.0	9.50	0.535	26	9.80
R1/5	Rippling	10.0	8.0	9.0	10.0	9.0	9.0	9.0	10.0	10.0	8.0	9.25	0.707		9.30
R1/5	Wear	9.0	8.0	7.0	8.0	8.0	8.0	8.0	8.0	9.0	7.0	8.00	0.535		8.80
R1/5	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000		9.98
R1/5	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
R2/6	Ridging	9.0	8.0	9.0	9.0	8.0	9.0	9.0	9.0	9.0	8.0	8.75	0.463	33	9.00
R2/6	Rippling	10.0	8.0	9.0	9.0	9.0	9.0	9.0	9.0	10.0	8.0	9.00	0.535		9.20
R2/6	Wear	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.00	0.000		6.30
R2/6	Spitting	3.0	3.0	3.0	2.0	3.0	2.0	3.0	1.0	3.0	1.0	2.50	0.756		2.33
R2/6	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
R3/7	Ridging	8.0	7.0	7.0	7.0	8.0	8.0	8.0	7.0	8.0	7.0	7.38	0.518	38	7.30
R3/7	Rippling	9.0	8.0	9.0	10.0	9.0	9.0	9.0	9.0	10.0	8.0	9.00	0.535		9.20
R3/7	Wear	6.0	7.0	6.0	6.0	7.0	7.0	6.0	6.0	7.0	6.0	6.38	0.518		6.70
R3/7	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.79	0.318		9.92
R3/7	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		
R4/10	Ridging	8.0	8.0	8.0	8.0	9.0	9.0	9.0	9.0	9.0	8.0	8.38	0.518	42	8.80
R4/10	Rippling	8.0	7.0	7.0	7.0	6.0	8.0	8.0	7.0	8.0	6.0	7.13	0.641		6.80
R4/10	Wear	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.0	6.00	0.000		6.00
R4/10	Spitting	9.9	9.9	9.8	9.8	9.9	9.8	9.0	9.6	9.9	9.0	9.71	0.304		9.80
R4/10	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000		

7
2008
2/13/08

ASTM Gear Calibration Workshop
Richmond, VA January 15, 16, 17 & 18, 2008

L-37 RING GEARS

SET #	DISTRESS	6	7	10	11	22	25	29	30	MAX	MIN	AVG	Std Dev
1C	Ridging	4.0	6.0	5.0	5.0	6.0	6.0	5.0	5.0	8.0	4.0	5.25	0.707
	Rippling	8.0	8.0	8.0	8.0	9.0	9.0	6.0	10.0	10.0	8.0	8.25	1.165
	Wear	5.0	6.0	5.0	5.0	7.0	7.0	6.0	7.0	7.0	6.0	6.00	0.926
	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
2C	Ridging	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
	Rippling	9.0	10.0	10.0	10.0	9.0	9.0	10.0	10.0	10.0	9.0	9.63	0.518
	Wear	6.0	8.0	8.0	9.0	8.0	7.0	8.0	8.0	9.0	8.0	7.75	0.886
	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
3C	Ridging	7.0	8.0	9.0	9.0	9.0	8.0	8.0	9.0	9.0	7.0	8.38	0.744
	Rippling	10.0	10.0	9.0	10.0	9.0	9.0	9.0	10.0	10.0	9.0	9.50	0.535
	Wear	7.0	8.0	8.0	8.0	9.0	7.0	7.0	8.0	9.0	7.0	7.75	0.707
	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
4C	Ridging	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
	Rippling	10.0	10.0	9.0	10.0	9.0	9.0	9.0	10.0	10.0	9.0	9.50	0.535
	Wear	8.0	7.0	8.0	9.0	8.0	8.0	7.0	8.0	9.0	7.0	7.88	0.641
	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
5	Ridging	3.0	3.0	3.0	3.0	4.0	3.0	4.0	4.0	4.0	3.0	3.38	0.518
	Rippling	7.0	8.0	10.0	9.0	9.0	10.0	9.0	8.0	10.0	7.0	8.75	1.035
	Wear	5.0	4.0	4.0	5.0	4.0	4.0	6.0	5.0	6.0	4.0	4.63	0.744
	Spitting	9.0	9.0	8.0	8.0	8.0	9.0	8.0	8.0	9.0	8.0	8.38	0.518
	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
6	Ridging	9.0	8.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	8.88	0.354
	Rippling	9.0	10.0	9.0	10.0	9.0	9.0	9.0	10.0	10.0	9.0	9.38	0.518
	Wear	7.0	7.0	6.0	6.0	7.0	7.0	7.0	7.0	7.0	6.0	6.75	0.463
	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
7	Ridging	8.0	7.0	8.0	8.0	8.0	9.0	10.0	9.0	10.0	7.0	8.38	0.916
	Rippling	9.0	9.0	10.0	10.0	9.0	9.0	9.0	9.0	10.0	9.0	9.25	0.463
	Wear	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.00	0.000
	Spitting	9.9	9.9	10.0	9.9	9.9	9.9	10.0	9.9	10.0	9.9	9.93	0.046
	Scoring	10.0	8.0	10.0	10.0	9.0	10.0	10.0	10.0	10.0	8.0	9.63	0.744
8	Ridging	9.0	9.0	9.0	9.0	10.0	9.0	10.0	9.0	10.0	9.0	9.25	0.463
	Rippling	10.0	10.0	10.0	10.0	10.0	9.0	10.0	10.0	10.0	9.0	9.88	0.354
	Wear	8.0	8.0	8.0	8.0	8.0	7.0	9.0	8.0	9.0	7.0	8.00	0.535
	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000

Attachment
Page 1672
Reference 2/13/08

ASTM Gear Calibration Workshop
Richmond, VA January 15, 16, 17 & 18, 2008

L-37 RING GEARS

SET #	DISTRESS	6	7	10	11	22	25	29	30	MAX	MIN	AVG	Std Dev
9	Ridging	9.0	9.0	9.0	9.0	10.0	9.0	10.0	9.0	10.0	9.0	9.25	0.463
9	Rippling	9.0	10.0	10.0	10.0	9.0	9.0	9.0	10.0	10.0	9.0	9.50	0.535
9	Wear	8.0	8.0	7.0	8.0	7.0	7.0	7.0	8.0	8.0	7.0	7.50	0.535
9	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
9	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
10	Ridging	10.0	10.0	10.0	9.0	10.0	10.0	10.0	10.0	10.0	9.0	9.88	0.354
10	Rippling	10.0	10.0	10.0	10.0	9.0	10.0	10.0	10.0	10.0	9.0	9.88	0.354
10	Wear	8.0	7.0	7.0	8.0	7.0	7.0	7.0	7.0	8.0	7.0	7.25	0.463
10	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
10	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
R1/5	Ridging	3.0	3.0	3.0	3.0	3.0	3.0	5.0	4.0	5.0	3.0	3.38	0.744
R1/5	Rippling	7.0	8.0	10.0	10.0	9.0	10.0	9.0	9.0	10.0	7.0	9.00	1.069
R1/5	Wear	5.0	5.0	3.0	3.0	5.0	4.0	6.0	5.0	6.0	3.0	4.50	1.069
R1/5	Spitting	9.0	9.0	8.0	8.0	8.0	9.0	8.0	8.0	9.0	8.0	8.38	0.518
R1/5	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
R2/8	Ridging	9.0	9.0	9.0	9.0	9.0	9.0	10.0	9.0	10.0	9.0	9.13	0.354
R2/8	Rippling	10.0	10.0	10.0	10.0	10.0	9.0	10.0	10.0	10.0	9.0	9.88	0.354
R2/8	Wear	8.0	7.0	8.0	8.0	8.0	7.0	8.0	8.0	8.0	7.0	7.75	0.463
R2/8	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
R2/8	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000
R3/9	Ridging	10.0	8.0	9.0	10.0	10.0	9.0	10.0	10.0	10.0	8.0	9.50	0.756
R3/9	Rippling	9.0	9.0	9.0	10.0	9.0	9.0	9.0	10.0	10.0	9.0	9.25	0.463
R3/9	Wear	8.0	7.0	7.0	8.0	7.0	7.0	7.0	8.0	8.0	7.0	7.38	0.518
R3/9	Spitting	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.90	0.000
R3/9	Scoring	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.00	0.000

Attachment 8
Page 267
Reference 2/2/08