



## Test Monitoring Center

© Carnegie Mellon University  
6555 Penn Avenue, Pittsburgh, PA 15206, USA

<http://astmtmc.cmu.edu>  
412-365-1000

ISB Information Letter 14-1  
Sequence No. 8  
November 10, 2014

*ASTM consensus has not been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.*

TO: Cummins Mailing List  
SUBJECT: Corrected Annotation of FIG. A4.7

It was discovered that there was an error in the annotation of FIG A4.7 describing the insertion depth of the thermocouple in the intake piping of ASTM Test Method D7484. FIG A4.7 has been updated to correct the error and is attached.

Dan Nyman  
Technical Advisor  
Chemical Technology & Lubricants  
Performance Testing  
Cummins Inc.

Frank M. Farber  
Director  
ASTM Test Monitoring Center

Attachment  
c: [ftp://ftp.astmtmc.cmu.edu/docs/diesel/cummins/procedure\\_and\\_ils/isb/il14-1.pdf](ftp://ftp.astmtmc.cmu.edu/docs/diesel/cummins/procedure_and_ils/isb/il14-1.pdf)

Distribution: Email

(Revises D 7484-13a)

Replace FIG. A4.7




FIG. A4.7 Location of Sensor for Intake Manifold Temperature Measurement