

Date: 14 APR 2004

To: ASTM Sequence III Testing Laboratories

From: Jason H. Bowden / OH Technologies, Inc.

Re: Seq. III CPD Technical Memo 9
BC 10, OH104 Main Flange Bearing Incorrectly Stamped

Cc: Mr. Sid Clark / General Motors Powertrain
Mr. Michael Kasimirsky / Test Monitoring Center

OH104 Main Flange Bearing Incorrectly Stamped

Please advise that the BC 10, OH104 Main Flange Bearing is incorrectly stamped "upper." The correct stamp should be "lower." This bearing meets all other specifications. OHT has taken corrective action for the future.

If there are any questions or comments regarding the aforementioned item, please do not hesitate to call.