



COAT Reference Oil Si Separation

10/29/20




© The Lubrizol Corporation. All rights reserved.



Discovery

- A reference test failed on 832-1
 - 11.8% at EOT (Target 10.23%)
- After a severity investigation Si levels were noted as being lower than typical








Follow Up Test Oil Drum Analysis

• Oil was sampled from the drum and then mixed with a blade mixer for 1 hour






© The Lubrizol Corporation. All rights reserved.



Follow Up Test Oil Analysis

• Higher initial Si levels are noted






prporation. All rights reserved.



Test Results Comparison

• Second test result of 11.4%





© The Lubrizol Corporation. All rights reserved.



MOVE CLEANER CREATE SMARTER





© The Lubrizol Corporation. All rights reserved.