

Test Monitoring Center

Carnegie Mellon University 6555 Penn Avenue, Pittsburgh, PA 15206, USA http://astmtmc.cmu.edu 412-365-1000

1P Information Letter No. 09-1 Sequence No. 6 August 24, 2009

ASTM consensus has not yet been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.

TO: Single Cylinder Diesel Mailing List

SUBJECT: Use of 1Y3997 Cylinder Liners

The use of 1Y3997 liners has been added to the 1P test procedure. The surface liner specification for the original 1Y3805 liners does not apply to the 1Y3997 liners. Sections 9.11 and 9.11.2 have been revised accordingly and are attached.

Hind Abi-Akar

Hind Abi-Akar Project Engineer Caterpillar, Inc. Frank M. Farber Administrator

ASTM Test Monitoring Center

Frank m Failer

Attachment

c: ftp://ftp.astmtmc.cmu.edu/docs/diesel/scote/procedure and ils/1p/il09-01.pdf

Distribution: Email

(Revises Test Method D6681-09)

- 9.11 Cylinder Liner—Use a new 1Y3805 or 1Y3997 cylinder liner for each test.
- 9.11.2 Measure and record the liner surface finish. The surface finish specification shown in Fig. A10.3 does not apply to the 1Y3997 cylinder liner.