

Mack T-10A Used Oil MRV

- Current procedure prescribes the use of D4684. If Yield Stress is observed, use Modified D-4684
- This procedure could delay obtaining a valid MRV result by several days
- Not all T-10A results have been obtained using the same procedure
- Task Force Recommendation:
 - Standardize on using the Modified D-4684 method in all cases
 - This method is being standardized : RR D02 1517