



Mack PC10 Engine Test Update



Ring & Liner Wear (Corrosive), Bearing Corrosion

- Mack T-12
- New Hardware (Piston / Liner / Ring)
- With ULSD Fuel
- Length - ~ 300 Hours
- Increased EGR Flow (Heavy EGR)
- Precision Matrix Required
- Hardware Available 2nd QTR