

The outage in May was due to a key feedstock being off specification (high in Sulfur) for an extended period of time. This was in line with a planned Unit Turnaround and a subsequent unplanned upset. As a result, supplies were affected.

Going forward, we anticipate that product supplies will be tight through 3Q06. While this could result in 1 – 2 day delays, our production schedule and feedstock availability is geared to cover demand.

Providing additional lead-time will be a good idea though in view of the tightness of product transportation equipment combined with the tight product supply situation. We don't want to over promise and under deliver but our efforts and plans revolve around supplying in a manner to avoid a repeat of the May '06 experience

Chevron Phillips Chemical Company LP
10001 Six Pines Drive, Suite 4036B
The Woodlands, Texas 77387-4910
(832) 813-4859
(832) 813-4907 (fax)
fuels@cpchem.com