



Oronite

Mack T8-E LTMS Modernization

Jim Rutherford


Mack Surveillance Panel November 2, 2016

Mack T-8E Current LTMS

y_i Limits ± 1.75



Oronite




Six failed reference attempts lab G. Eight failed reference attempts lab J.

Mack T-8E Current LTMS

Z_i Limits ± 0.653 for SA



Oronite




Mack T-8E Modernized LTMS



Oronite

e_j Limits ± 2.066




Six failed reference attempts lab G. Ten failed reference attempts lab J.

Mack T-8E Modernized LTMS

Z_i with continuous SA and EI adjustment



Oronite




Mack T-8E Modernized LTMS



Oronite

t_i with SA adjust forward current vs. modernized




Mack T-8E Modernized LTMS

t_i with SA adjust forward current vs. modernized



Oronite



Mack T-8E Modernized LTMS

t_i with SA adjust forward current vs. modernized



Oronite

