MEMORANDUM: 03-059

DATE: June 2, 2003

TO: RFWT Surveillance Panel

FROM: Jeff Clark

SUBJECT: RFWT Engine Numbering

It has been brought to the attention of the Test Monitoring Center that five sets of roller followers have been etched with previously designated engine numbers. The sets in question are 103 through 107. To avoid any possible problems caused by the duplicate numbering, these sets are to have an 'A' suffix added to them for reporting purposes. Subsequently, these five sets will be referred to as 103A through 107A.

Please contact me if you have any questions.

c: ftp://ftp.astmtmc.cmu.edu/docs/diesel/rfwt/memos/mem03-059.pdf

Distribution: Email