

Date: March 5, 2007

To: ASTM Sequence III Testing Laboratories

From: Adam D. Bowden / OH Technologies, Inc.

Re: Seq. III CPD Technical Memo 11
OHT3F-030-2, MODIFIED OIL COOLER, INCORRECT LASER MARKINGS

Cc: Mr. Sid Clark / General Motors Powertrain
Mr. Rich Grundza/ Test Monitoring Center

OHT3F-030-2, COOLER OIL, INCORRECT LASER MARKINGS

Please be advised that eighteen (18) parts shipped with incorrect laser markings. Parts that show the following markings are etched incorrectly:

OHT3F-030-2
M= 020813
C/SP= 060629
BYPASS CLOSED

Note that the number sequence above is unique and traceable to these parts and the destination of these parts is on record at OH Technologies and notations have been made.

The correct markings should have been:

OHT3F-030-2
M= 060629
C/SP= 070215
BYPASS CLOSED

Future shipments will have the correct batch markings.

If there are any questions or comments regarding the aforementioned item, please do not hesitate to call.