

Date: February 21, 2008

To: ASTM Sequence III Testing Laboratories

From: Jason H. Bowden / OH Technologies, Inc.

Re: Seq. III CPD Technical Memo 12
3F05X-01, RAIL, OIL – BATCH CODE 13 – GAP INSPECTION

Cc: Mr. Sid Clark / General Motors Powertrain
Mr. Rich Grundza/ Test Monitoring Center

3F05X-01, RAIL, OIL – BATCH CODE 13 – GAP INSPECTION

Please be advised that one lab has identified approximately twelve oil rails that have abnormal gaps (i.e. oversized and / or gaps that were not square)

If laboratories identify any 3F05X-01 OIL RAILS that they deem suspect, please return this material to OH Technologies, Inc. for full inspection / replacement.

OH Technologies, Inc. is currently working with our vendor to determine the root cause for this error. Corrective action will be taken.

If there are any questions or comments regarding the aforementioned item please do not hesitate to call.