

Date: December 12, 2008

To: ASTM Sequence III Testing Laboratories

From: Dwight Bowden / OH Technologies, Inc.

Re: Seq. III CPD Technical Memo 15  
OHT3G-057-3 Filter, Oil BATCH CODE 5

Cc: Mr. Bruce Matthews / General Motors Powertrain  
Mr. Rich Grundza/ Test Monitoring Center

Mr. Ed Altman of Afton brought to our attention that the aforementioned material contains significant design changes from previous material that may result in the filter going into premature bypass.

OH Technologies purchase orders for this component is explicit as to part number and manufacturing location as a means of insuring consistency from batch code to batch code. The vendor did not comply with purchase order specifications for Batch Code 5. In addition, OHT did not recognize the error upon receipt of material.

The vendor has been made aware of the situation. Replacement material of the correct design will be at our location Monday, 12/15/2008. This material is to be designated Batch Code 6. In addition, OH Technologies has executed a life of test build out order for this component.

Please return freight collect all Batch Code 5 oil filters for replacement. If there are any questions, please do not hesitate to call.

I sincerely regret this error.