

Date: January 6, 2009

To: ASTM Sequence III Testing Laboratories

From: Dwight Bowden / OH Technologies, Inc.

Re: Seq. III CPD Technical Memo 16
OHT3F-028-2 BUSHING, ROCKER COVER, ONE PIECE DESIGN

Cc: Mr. Bruce Matthews / General Motors Powertrain
Mr. Rich Grundza/ Test Monitoring Center

This Technical Memo is issued in accordance to the consensus position of the Sequence III Surveillance Panel meeting of 11/13/2008. The panel approved the removal of the roll pin stop from the aforementioned part as this component may separate from the assembly, enter the engine crankcase and potentially damage the engine during operation. It was determined that the rocker cover bushing assembly is functional without the roll pin installed.

Therefore:

- 1.) Laboratories should remove the roll pin stop from their inventory of this part.
- 2.) OH Technologies, Inc. will remove the roll pin stop from parts held in inventory.
- 3.) OH Technologies, Inc. will revise drawing removing the roll pin stop.

If there questions regarding is matter please do not hesitate to call.