

Date: October 20, 2011

To: ASTM Sequence III Testing Laboratories

From: Jason Bowden / OH Technologies, Inc.

Re: Seq. III CPD Technical Memo 21
OHT3F-008-8 camshafts

Cc: Mr. Bruce Matthews / General Motors Powertrain
Mr. Rich Grundza/ Test Monitoring Center

This Technical Memo is intended to notify users of the Sequence III test methods that we have confirmed several camshafts are out of specification up to .002 inch, with regards to the thrust face run out. This may cause a reduction in end play. OH Technologies will be notifying individual labs of specific camshaft serial numbers in their inventory to be returned to OH Technologies for inspection. OH Technologies, Inc. has taken corrective action with the vendor and has eliminated the possibility of these camshafts being shipped in the future.

If there are any questions or comments regarding the aforementioned item please do not hesitate to call.

Jason H. Bowden
OH Technologies, Inc.