



Test Monitoring Center

6555 Penn Avenue
Pittsburgh, PA 15206-4489
(412) 365-1000

SEQUENCE VIB INFORMATION LETTER 07-1
SEQUENCE NUMBER 23
August 6, 2007

ASTM consensus has not been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.

TO: Sequence VIB Mailing List
SUBJECT: Additional Spark Plug Part Number

Recently, the Sequence VIB Surveillance Panel was informed that several spark plugs are no longer available from the supplier. As a result, a new spark plug part number, SP432, has been added to the approved parts list. Revised Section 9.3.16.4 of Test Method D 6837 is attached.

These changes are effective the date of this information letter.

Ronald Romano
Product Engineering
Ford Motor Company

John L. Zalar
Administrator
ASTM Test Monitoring Center

Attachment

c: ftp://ftp.astmtmc.cmu.edu/docs/gas/sequencevi/procedure_and_ils/il07-1.pdf

Distribution: Email

Revises Test Method D 6837-06

9.3.16.4 *Spark Plugs*—Use spark plugs, Part No. AWSF32C, AWSF32P, AGSF32PB, AGSF32FM or SP432. Spark plug gap shall be 1.31 to 1.41 mm (0.052 to 0.056 in.).