



Test Monitoring Center

@ Carnegie Mellon University
6555 Penn Avenue, Pittsburgh, PA 15206, USA

<http://astmtmc.cmu.edu>
412-365-1000

Sequence VIE Information Letter 19-2
Sequence Number 5
April 11, 2019

ASTM consensus has not been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.

TO: Sequence VI Surveillance Panel
SUBJECT: Clarification of additional Break-in

During the March 22, 2019 Sequence VI Surveillance Panel Conference call, the panel agreed to clarify the additional break in as it relates to anomalous results. Section 10.1.18 has been revised to better describe the process and circumstances for conducting additional break-in.

These revised text and or section(s) have been highlighted in red and are effective with the issuance of this letter.

Michael P. Raney
Engine Oil Test Development and Support
GM Global Propulsion Systems

Frank M. Farber
Director
ASTM Test Monitoring Center

Attachment

c: http://www.astmtmc.cmu.edu/ftp/docs/gas/sequencevi/procedure_and_ils/VIE/il19-2_vif.pdf

Distribution: Email

Revises D8114-18a as amended by Information Letters 18-2, 18-3, 18-4, and 19-1

10.1.1.8 For an engine to be considered new for calibration purposes following an anomalous reference oil test result, a lab must run a minimum of an additional 50 h of break-in.