



## Test Monitoring Center

@ Carnegie Mellon University  
6555 Penn Avenue, Pittsburgh, PA 15206, USA

<http://astmtmc.cmu.edu>  
412-365-1000

Sequence VIE Information Letter 20-4  
Sequence Number 10  
September 14, 2020

TO: Sequence VI Surveillance Panel  
SUBJECT: Correction to FEI2 Engine Hour Correction Multiplier

During the September 8, 2020 Sequence VI Surveillance Panel Conference call, it was brought to the panel's attention that the multiplier for FEI2 engine hour correction was wrong. Equation A15.7 referenced the same multiplier, 0.00518 as equation A15.6. Equation A15.7 has been corrected to show the correct multiplier, 0.000381.

Attached is the revised equation of Test Method D8114. This change is effective with the issuance of this letter.

Aleise Gauer  
Materials Engineer – Fluids & Lubricants  
GM Global Propulsion Systems

Frank M. Farber  
Director  
ASTM Test Monitoring Center

Attachment

c: [http://www.astmtmc.cmu.edu/ftp/docs/gas/sequencevi/procedure\\_and\\_ils/VIE/il20-4\\_vie.pdf](http://www.astmtmc.cmu.edu/ftp/docs/gas/sequencevi/procedure_and_ils/VIE/il20-4_vie.pdf)

Distribution: Email

**Revises D8114-20 as Amended by Information Letters 20-2 and 20-3**

$$(FEI2)_{\text{adjusted}} = FEI2 + \{0.000381 \times [(EH_{\text{EOT}}) - 675]\}$$

(A15.7)