MEMORANDUM: 05-010

DATE: April 6, 2005

TO Charlie Leverett, Chairman, Sequence VIB Surveillance Panel

FROM: Richard Grundza

SUBJECT: Sequence VIB Test Results from October 1, 2004 through March 31, 2005


The following is a summary of Sequence VIB reference tests that were reported to the Test Monitoring Center during the period October 1, 2004 through March 31, 2005.

Lab and Stand Summary

	Reported Data During Period	Calibrated as of 03/31/2005
Laboratories	7	7
Stand/Engine Combinations	22	11

The following chart shows the laboratory stand/engine distribution for data reported during this report period:


□ Current Period■ Previous Period



The following summarizes the status of the reference oil tests reported to the TMC this report period.

	TMC Validity Codes	No. of Tests
Operationally and Statistically Acceptable	AC	33
Failed Acceptance Criteria	OC	3
Failed Acceptance Criteria (Not in Charts)	OC	3
Operationally Invalid (Laboratory Judgement)	LC	3
Aborted	XC	1
Total		43


Attempted calibration tests are depicted graphically below by report period:



The calibration per start rate has increased with respect to the previous period and is the highest rate to date. The rejected per start rate has decreased, while the lost test per start rate has increased, when compared to the previous report period.


The percentage of tests failing the acceptance criteria for operationally valid tests has increased when compared to the previous period. The percentages are depicted graphically below.

Rejected Operationally Valid Tests




Distribution of LTMS Stand Alarms

Distribution of Stand Alarms by Parameter




There were two tests rejected for FEI Shewhart (Yi) severe, two tests rejected for FEI Shewhart (Yi) mild, and two tests rejected for EWMA precision alarm (Qi). Of the three tests that were run for calibration and were not charted, two were severe on FEI1 and FEI2. The other test was mild on FEI1 and FEI2. There has not been a LTMS deviation written for Sequence VIB to date.

The laboratory distribution of lost tests is shown below. A detailed list of reasons for tests declared operationally invalid, aborted or lost due to abandoned engines is shown in Table 2 (See Attachment).




The average oil consumption by oil and laboratory are depicted graphically below. Shown below is a summary of the average oil consumption for all laboratories reporting data this report period.




TEST SEVERITY AND PRECISION


The industry mean Δ /s for FEI1 and FEI2, for this report period are -0.07 and -0.10 severe, respectively.




Shown below is a summary of the average FEI Δ /s for all laboratories reporting data this report period.



The industry precision estimates for FEI1 and FEI2 for this report period are 0.20 and 0.20 (pooled s), respectively. Precision for both FEI1 and FEI2 have not changed when compared to the previous period and compared well with historical estimates.





^{*}Precision estimates are calculated by pooling oil and stand/engine combination.

INDUSTRY CONTROL CHARTS

FEI1

Figure 1 (the last 75 test results) shows FEI1 severity in control the entire period. FEI1 precision began the period in alarm, sounding two action alarms, followed by a series of five warning alarms. The charts clear for a test before sounding two additional warning alarms, the charts then clear for the remainder of the period. Precision alarms appeared to be the result of a number of severe tests from new/stand engines, intermixed with on target to mild results from existing stands. Figure 2 shows the entire industry chart.

FEI2

Figure 3 (the last 75 test results) shows severity and precision in control for the entire period. Figure 4 shows the entire industry chart.

REFERENCE OILS

The following table quantifies reference oils by the number of tests remaining at the TMC and each laboratory. Sequence VIB reference oils are shipped in quantities of 5 gallons per test.

LAB	538	539	1006	1007	1008	1008-1
A	3	1	0	7	0	3
В	2	1	0	2	0	2
С	1	1	0	2	0	2
D	1	0	0	0	0	1
F	1	1	0	3	0	1
G	3	1	0	2	0	3
L	2	1	0	5	0	1
TMC	88	182	0	*	**	***

- * 457 Gallons (Multiple test area usage)
- ** 29 Gallons (Multiple test area usage)
- *** 1584 Gallons (Multiple test area usage)

LAB VISITS

Two lab visits were conducted during this report period. Any discrepancies noted during these visits have been identified to the laboratory and the appropriate corrective actions taken have been documented.

INFORMATION LETTERS

Information Letters 04-4 and 04-5 were issued this report period. Information Letter 04-4, issued November 15, 2004, allows the use of an external flush cart to flush the coolant system of a newly installed engine. Information Letter 04-5, issued December 14, 2004 clarified the requirement for solvents to meet ASTM D235, Type II Class C. The method now requires that the solvent meet ASTM D235, Type II, Class C specifications for Aromatic Content, Color and Flash Point only.

SUMMARY

Severity for FEI1 was severe this report period.

Severity for FEI2 trended severe for this report period.

FEI1 and FEI2 precision has not changed when compared to the last report period.

The percentage of calibrations per starts has increased this report period.

The percentage of lost tests per starts has decreased this report period.

The percentage of statistically rejected tests per starts has decreased this report period.

The percentage of operationally valid tests rejected statistically has decreased this report period.

REG/reg

Attachments

c: Sequence VIB Surveillance Panel
 Sequence VIB Test Engineers
 ftp://ftp.astmtmc.cmu.edu/docs/gas/sequencevi/semiannualreports/vib-04-2005.pdf

Sequence VIB Semiannual Report List of Attachments

- -- Table 1 is a historic statistical summary for reference oils through March 31, 2005.
- -- Table 1A is a statistical summary for reference oils for the current report period.
- -- Table 2 is a summary of lost tests due to operationally invalid, aborted, abandoned engines or lost due to BC shift exceeding the test limits.
- -- Table 3 is the Sequence VIB Timeline.
- -- Figure 1 graphically present the Industry control charts for FEI1 for the last 75 test results.
- -- Figure 2 graphically present the Industry control charts for FEI1.
- -- Figure 3 graphically present the Industry control charts for FEI2 for the last 75 test results.
- -- Figure 4 graphically present the Industry control charts for FEI2.

TABLE 1

SEQUENCE VIB OPERATIONALLY VALID DATA SET DATA PRIOR TO 04/01/05

OIL CODE 1006

N 	TEST PARAMETER	MEAN	S 	REPORTED RANGE
236 236	FEI1 FEI2	1.40 0.52	0.29	0.61 - 2.50 36 - 1.23
		OIL COL	DE 1007	
N 	TEST PARAMETER	MEAN	s	REPORTED RANGE
92 92	FEI1 FEI2			0.24 - 2.11 55 - 1.25
		OIL COI	E 1008	
N	TEST PARAMETER	MEAN	S	REPORTED RANGE
245	FEI1 FEI2	1.82 1.24		1.18 - 2.47 0.58 - 1.74
		OIL COD	E 1008-1	
N	TEST PARAMETER	MEAN	S	REPORTED RANGE
166 166	FEI1 FEI2		0.25 0.23	1.24 - 2.55 0.48 - 1.95
		OIL COD	DE 538	
N	TEST PARAMETER	MEAN	s	REPORTED RANGE
194 194	FEI1 FEI2	1.86	0.32	0.86 - 2.67 0.93 - 2.32

933 TOTAL

TABLE 1A

SEQUENCE VIB OPERATIONALLY VALID DATA SET DATA FROM 10/01/04 THRU 03/31/05

		OIL CODE	1008-1	
N	TEST PARAMETER	MEAN	s	REPORTED RANGE
21 21	FEI1 FEI2	1.87 1.22	0.26 0.23	1.25 - 2.19 0.48 - 1.56
		OIL CODE	538	
N	TEST PARAMETER	MEAN	s	REPORTED RANGE
18 18	FEI1 FEI2	1.96 1.60	0.24	1.61 - 2.46 1.23 - 2.08

39 TOTAL

Table 2

Lost Tests Summary

Tests declared operationally invalid, aborted or lost due to abandoned engines are summarized below by laboratory, reason, number of lost tests, and percent of lost tests:

LAB	REASON	Tests Lost	% of Tests Lost
G	EBP control problems Load cell failure	1	25.0% 25.0%
	Exceeded procedurally allowed number of shutdowns	1	25.0%
L	Timing Chain Failure on New Engine	1	25.0%

Sequence VIB Timeline

Date	Item Changed	Information Letter
19990809	Reference oil 1006 targets updated	Letter
19990809	Reference oil 1007 targets updated	
19990809	Reference oil 1008 targets updated	
19990924	Calibration requirements	99-1
19990924	Alternative Cooling system	99-1
19990924	Fuel injection flow procedure	99-1
19990924	Requirement for use of maintenance log	99-1
19990924	Coolant flow measurement device calibration revision	99-1
19990924	Preparation procedure for oil charge	99-1
19990924	Recording compression pressures	99-1
19990924	Ignition timing checks	99-1
19990924	Valve stem seal replacements	99-1
	*	99-1
19990924 19990924	Alternative Racor oil filter (LFS-62) use approved	99-1
	Engine serial number added to report Invalid test BC shift limits of –0.5 to 0.8% added	
19991015		99-2
19991015	Tests terminated due to an FEI result are not permitted	99-2
19991015	Section 11.5.17.3 deleted – Manual data logging no longer required	99-2
19991015	Exhaust back pressure calibration prior to calibration test added	99-2
19991015	Instrumentation calibration requirements	99-2
19991015	Use of Eaton 37KW (50hp) dry gap dynamometer approved	99-2
19991015	New flush oil (BCFHD) and flush oil procedure	99-2
19991015	Micro motion model CMF010 mass flow meter approved	99-2
19991015	Kinematic viscosity measurements on new reference oils permitted	99-2
19991015	Report form editorial change for LABVALID made	99-2
19990924	Valve stem seal revised part number	99-3
20000207	Oil sight glass calibration	00-1
20000207	Revised Figure A2.22 – Oil Level Marker Ruler	00-1
20000207	Revised flush effectiveness procedure	00-1
20000207	Coolant flush procedure	00-1
20000207	Oil consumption validity interpretation	00-1
20000207	Load cell temperature specification	00-1
20000410	Valve Spring Replacement	00-2
20000524	Eliminate Baseline Shift Criteria	00-3
20000601	Maximum Allowable Oil Consumption Test Limit	00-3
20000601	Oil Sample Location Defined	00-3
20000601	Revised Blow-by and Crankcase Ventilation System	00-3
20000807	Fuel Injector Calibration Flow Rate Specification Added	00-3
20000807	Dynamometer Replacement During a test is not permitted	00-3
20000807	Engine Break-in Stand Requirements	00-3
20000807	Removal of Ford Wiring Harness Diagram	00-3
20000807	Addition of Alternative Injector Wiring Harness Part Numbers	00-3
20000807	Addition of Alternative HEGO Sensor Part Numbers	00-3
20000807	Addition of Alternative Throttle Body Adapter Part Number	00-3
20000807	Visteon EEC Control Module	00-3
20000901	Barometric Pressure added to report packet as record only	00-3

Sequence VIB Timeline


		Information
Date	Item Changed	Letter
20000801	A Task Force Was Appointed by the VIB Surveillance Panel to Address Lab	
	To Lab Differences with Oil Consumption and FEI Severity. Information	
	Letter 00-4 was a result of the Lab Visit Discrepancies.	
20000915	Increase Oil Charge to 6.0 Liters	00-4
20000915	Revise Oil Level/Sight Glass Calibration Procedure	00-4
20000915	Oil Pan Oil Level Requirement	00-4
20001116	Reduced Calibration Frequency	01-1
20001117	Validity Interpretation During BSFC Measurement Cycle	01-1
20001117	Reporting Stage Restarts or Any Test Time Deviations	01-1
20001117	Alternate HEGO Sensor Part Number	01-1
20001117	Revisions to New Engine Cyclic Break-in	01-1
20010301	Revisions to Test Length Calculation and Reporting Format	01-1
20010301	Additional Oil Analysis Requirements	01-1
20010822	Allowed Timing Chain Tensioner with Subsequent Reference Oil Test	01-2
20010822	Defined Maximum Total Test Length as 150 h	01-2
20010822	Defined Off Test Time and Allows No More Than 2 h of Off Time During	01-2
	Phase I and II Aging	
20010822	Added Reference to Ford 543 Engine Assembly Manual	01-2
20010822	Refined Oil Analysis Procedure for HTHS, CCS Viscosity, Friction Coefficient	01-2
	by HFRR, Fuel Dilution and Infrared for Oxidation & Nitration	
20010822	Correction of Company Suppliers in X1.3 and X1.19	01-2
20011005	Pressurization of Engine Coolant System to 69±13.8 kPa	01-3
20011005	Deleted Requirement to Measure Blowby	01-3
20011005	Revised Load Cell Temperature Delta for 3°C to 6°C in 6.4.2.3	01-3
20011005	Corrected Fuel Supplier Name and Address in Section 7.2 and Footnote 15	01-3
20011129	Added Provisions for VIBSJ Test	01-4
20011207	Revised AFR limits from 14.25:1 - 15.25:1 to 14.00:1 – 15.00:1	01-5
20020405	Allowed Replacement of Timing Chain as Part of Tensioner Assembly	02-1
20020405	Revised Procedure to Require Viscosity Measurements for Both Reference	02-1
	and Non Reference Oils	V
20020712	Reference oil 538 targets updated (n=20)	
20021016	Reference oil 538 targets updated (n=30)	
20021114	Reference oil 1008-1 initial targets generated (n=10)	
20030327	Updated Test Method D6837 to incorporate info letter 02-1 and remove	03-1
	remedial statements	00 1
20030521	Reference oil 1008-1 initial targets generated (n=20)	
20030618	Dropped requirements to monitor HTHS, CCS, FC by HFRR and INI and	03-2
20030010	INO	03 2
20030703	Reference oil 1008-1 initial targets generated (n=30)	
20030703	Added reference to fuel spec, replaced Aliphatic Naphtha with Type II Class	03-3
∠ 00-T0101	C solvent	05-5
20040130	Added addition micromotion transducers to test method, revised calibration	04-1
200 1 0130	requirements for oil heat exchanger thermocouple and made editorial changes	04-1
	relating to precision statements.	
20040802	Added MotorCraft AGSF32FM to test method	04-2
20040802	Audeu Motorciait Auseszeini to test method	U4-Z


Sequence VIB Timeline

	•	Information
Date	Item Changed	Letter
20040802	Added rear crankshaft seal to parts allowed to be replaced on engine	04-2
20040802	Made editorial changes to precision statement	04-2
20040921	Changed Z ₀ calculation to be the average of first shewhart acceptable through	
	and including second acceptable reference test to initialize stand charts. Also	
	excluded any unacceptable shewhart results, prior to the first acceptable result	
	on a new stand/engine from control charts.	
20041001	Revised stand/engine calibration requirements to include engine test hours	04-3
20041001	Change calibration frequency for fuel flow, speed, AFR and EBP to prior to a	04-3
	reference sequence.	
20041001	Decreased calibration frequency for coolant flow, thermocouple &	04-3
	temperature measurement systems and other instrumentation to every six	
	months	
20041115	Added provisions for external coolant flush cart	04-4
20041214	Clarified Requirement for solvent meeting ASTM D235, Type II, Class C to	04-5
	meet Type II, Class C requirements for Aromatic content, Color and Flash	
	point only.	


SEQUENCE VIB INDUSTRY OPERATIONALLY VALID DATA

Last 75 Tests





SEQUENCE VIB INDUSTRY OPERATIONALLY VALID DATA Figure 3



SEQUENCE VIB INDUSTRY OPERATIONALLY VALID DATA

