



## Test Monitoring Center

6555 Penn Avenue  
Pittsburgh, PA 15206-4489  
(412) 365-1000

L-33-1 Information Letter No. 03-1  
Sequence No. 2  
May 7, 2003

***ASTM consensus has not yet been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.***

TO: L-33-1 Mailing List

SUBJECT: 1. Revised Test Unit Assembly Procedure  
2. Revised Specification for the Abrasive Blasting Cabinet Regulator  
3. Revised Electric Fan Motor RPM Specification  
4. Non-interpretable Tests  
5. Revision to Light Rust Definition  
6. Editorial Revisions

1. At the January 29, 2003 Surveillance Panel meeting the panel approved a revised test unit assembly procedure. Section 9.2.2 of the L-33-1 Test Procedure has been completely revised.

2. At the January 29, 2003 Surveillance Panel meeting the panel approved a motion to revise the specification for the abrasive blasting cabinet regulator to  $80 \pm 2$  psig. Section 6.2.9.1 of the L-33-1 Test Procedure has been revised.

3. At the April 8, 2003 L-33-1 Surveillance Panel meeting, the panel approved a motion to revise the electric fan motor specification to  $1700 \pm 100$  r/min. Section 6.2.7 of the L-33-1 Test Procedure has been revised.

4. At the April 8, 2003 L-33-1 Surveillance Panel meeting, the panel approved a motion that any non-reference oil test that has not been run in a calibrated test stand and/or not conducted on approved hardware be considered non-interpretable. The cover page of the test report shall indicate that the test is non-interpretable and has not been conducted in a valid manner in accordance with the L-33-1 Test Procedure. A new Section 10.1.4 has been added to the L-33-1 Test Procedure.

5. At the April 8, 2003 L-33-1 Surveillance Panel meeting, the panel approved a motion to revise the light definition for rust. Section 12.2 of the L-33-1 Test Procedure has been revised.

6. At the April 8, 2003 L-33-1 Surveillance Panel meeting, the panel approved a motion to include the editorial changes made by the L-33-1 Surveillance Panel and Facilitator in the L-33-1 Test Procedure.

The revised test procedure can be downloaded from the Test Monitoring Center website at:

[ftp://ftp.astmtmc.cmu.edu/docs/gears/l331/procedure\\_and\\_ils/L-33-1\\_Procedure\\_20030505.pdf](ftp://ftp.astmtmc.cmu.edu/docs/gears/l331/procedure_and_ils/L-33-1_Procedure_20030505.pdf)

These changes are effective the date of this information letter.



Dale Smith  
Chairman  
L-33-1 Surveillance Panel



John L. Zalar  
Administrator  
ASTM Test Monitoring Center

c: [ftp://ftp.astmtmc.cmu.edu/docs/gears/l331/procedure\\_and\\_ils/il03-1.pdf](ftp://ftp.astmtmc.cmu.edu/docs/gears/l331/procedure_and_ils/il03-1.pdf)

Distribution: Email