



Test Monitoring Center

6555 Penn Avenue
Pittsburgh, PA 15206-4489
(412) 365-1000

L-37 Information Letter 07-1
Sequence Number 36
July 16, 2007

ASTM consensus has not been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.

TO: L-37 Mailing List
SUBJECT: Revised Calibration Requirement

At the June 27, 2007 L-37 Surveillance Panel meeting, the panel approved a motion to suspend the requirement of alternating lubrited and non-lubrited hardware with each reference oil calibration sequence. This action became necessary due to pitting/spalling and ridging severity issues with the new lubrited hardware gear batch B6L566/P4L816 and a shortage of previously approved lubrited hardware. This requirement will be reinstated once lubrited hardware becomes available. Section 9.2.6 of Test Method D6121 has been deleted and Section 9.2.7 will be renumbered to 9.2.6.

The effective date for these changes is June 27, 2007.

Don Bartlett
Chairman
L-37 Surveillance Panel

John L. Zalar
Administrator
ASTM Test Monitoring Center

Attachment

c: ftp://ftp.astmtmc.cmu.edu/docs/gear/1-37/procedure_and_ils/il07-1.pdf

Distribution: Electronic Mail

(Revises Test Method D 6121-06a)

Delete Section 9.2.6

Renumber 9.2.7 to 9.2.6