



Test Monitoring Center

@ Carnegie Mellon University
6555 Penn Avenue, Pittsburgh, PA 15206, USA

<http://astmtmc.cmu.edu>
412-365-1000

L-37 Information Letter 13-3
Sequence Number 47
April 24, 2013

ASTM consensus has not been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.

TO: L-37 Surveillance Panel

SUBJECT: Inspection port

At its November 7, 2012 meeting, the L-37 Surveillance Panel revised D 6121 wording to indicate the installation of an inspection port in the axel cover was optional. Section 6.2.2 has been updated as shown in the attachment.

This change is effective as of November 7, 2012.

Chris Prengaman
Chairman
L-37 Surveillance Panel

Frank Farber
Director
ASTM Test Monitoring Center

Attachment

cc: ftp://ftp.astmtmc.cmu.edu/docs/gear/137/procedure_and_ils/il13-3.pdf

Distribution: Email

(Revises Test Method D 6121-12B as modified by Information Letters 13-1 and 13-2)

6.2.2 Axle Cover - The axle cover may have a port installed to allow for ring gear inspection after the gear conditioning phase (see 10.1). See Fig. A2.1 for an example.