

**L42-1 task force conference call
9-29-2005**

C. Koglin
B. Koehler
D. Lind
D. Smith
D. Bartlett

- SWRI to send TF plot of temperature vs Time for entire L42-1 test
- Don Lind to send Shock 1 and Shock 2 drive side torques to TF
- SWRI drawings to be completed and sent to TMC by October 14th

1 lab continues to have trouble with power and control of shock series

A reoccurring conference call was setup every Thursday at 2pm EDT for L42-1 issues.

L42 Low Temperature matrix update

SWRI waiting on PO's