

**L331 Timeline**

<b>Obs</b>	<b>effective_date</b>	<b>info_letter_number</b>	<b>event</b>
1	20030106	02-1	New L-33-1 Test Procedure
2	20030507	03-1	Revised test unit assembly procedure
3	20030507	03-1	Revise specification for the abrasive blasting cabinet regulator
4	20030507	03-1	Revised electric fan motor RPM specification
5	20030507	03-1	Non-interpretable tests
6	20030507	03-1	Revision to light rust definition
7	20030507	03-1	Editorial changes
8	20030916	03-2	Bearing replacement
9	20030916	03-2	Addition of Dana bulletin No. 5304-2
10	20040101	03-2	Change in solvent specification
11	20050221	05-1	Revised Solvent Specification
12	20050221	05-1	Revised Cover Plate Guide Pin Requirement
13	20050221	05-1	Updated Test Precision
14	20050221	05-1	Donated Reference Oil Test Programs/Calibration Period Length Adjustment
15	20050221	05-1	Revised Footnote 2
16	20060207	06-1	Axle Cover Rating Template
17	20060721	06-2	Housing Cover Gasket Supplier Name and Address Change
18	20061009	06-3	Aluminum Differential Case, Area 2, Hub Inside Diameter Rating Template
19	20061009	06-3	Editorial changes
20	20070214	07-1	Revised Area 1 Rating Surface Description
21	20070214	07-1	Editorial Changes to Figures A1.8, A1.14, and A1.15
22	20070411	07-2	Editorial Changes to Sections A2.2.1 and A2.2.2
23	20070525	07-3	Rating Procedure Using Aluminum Differential Case, Area 2, Hub Inside Diameter Rating Template
24	20071114	07-4	Revised Start-up Procedure
25	20080114	08-1	Revised Section 11.1.6.1
26	20090323	09-1	Revision to Percent Deviation Calculation