



Test Monitoring Center

@ Carnegie Mellon University
6555 Penn Avenue, Pittsburgh, PA 15206, USA

<http://astmtmc.cmu.edu>
412-365-1000

1K/1N Information Letter No. 18-1
Sequence No. 41
May 7, 2018

ASTM consensus has not yet been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.

TO: Caterpillar Surveillance Panel Mailing List
SUBJECT: Correction to 1K/1N Liner Requirements

1K/1N Information Letter 09-2, Sequence No. 30, when originally issued and subsequently incorporated into D 6750-09, omitted the removal of the need to take liner surface measurements. Since liner surface measurements are not required for the 1Y3998 liner section 9.3.4.1 has been updated.

Section 9.3.4.1 has been corrected accordingly and is attached.

Hind Abi-Akar

Hind Abi-Akar
Project Engineer
Caterpillar, Inc.

Frank M. Farber
Director
ASTM Test Monitoring Center

Attachment

cc: http://www.astmtmc.cmu.edu/ftp/docs/diesel/CAT/procedure_and_ils/1k-1n/il18-01.pdf

Distribution: Email

(Revises Test Method D6750-17 as amended by IL17-1)

9.3.4.1 Oil the liner bore with Exxon-Mobil EF-411 oil.