## CAT 1N Industry Correction Factor




## James McCord



June 22,2004

## CAT 1N Hardware Change

- As of 5/31/04, the 1Y3998 liner has replaced the 1Y3555 liner for use in the CAT-1N
- Based on 5 data points, 1Y3998 liner required a TLHC industry correction factor of –1.135 (transformed value)
- TGF appeared to be mild, but, no action will be taken until the p value is less than 0.05
- 5 additional tests will be run in December 04 to verify the severity of the CAT-1N



## CAT 1N Effective Pass Limit

| Parameter | ASTM<br>1st Test Limit | Effective<br>Pass Limit |
|-----------|------------------------|-------------------------|
| TLHC      | 3                      | 13                      |
| BSOC      | 0.5                    | 0.5                     |
| TGF       | 20                     | 20                      |
| WDN       | 286.2                  | 286.2                   |

