

Date: April 12, 2017

To: ASTM Testing Laboratories

From: Jason Bowden / OH Technologies, Inc.

Re: CPD Technical Memo 01
Seq. IIIH Second Ring Gap, Batch Code 4

Cc: Mr. Rich Grundza/ Test Monitoring Center

This Technical Memo is intended to notify users of the ASTM Seq. IIIH Testing Method of a concern regarding gap squareness on a limited quantity of 2nd rings. OHT is currently having sample material inspected at our vendor.

OHT is requesting that labs return any suspect, Batch Code 4, Seq. IIIH Second Ring material for inspection and immediate replacement.

We apologize for any inconvenience this may cause and will be taking prompt corrective action.

If there are any questions or comments regarding the aforementioned item, please do not hesitate to contact me.

Jason H. Bowden
OH Technologies, Inc.