



Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

Sequence IIIH Information Letter 22-3
Sequence Number 23
September 19, 2022

TO: Sequence III Surveillance Panel

SUBJECT: Correction to Table reference in Section 10.4.6.1

Recently, it was brought to the attention of the Sequence III Surveillance Panel that Section 10.4.6.1 references to Table 6 incorrectly. The correct table should be Table 5. The attached corrected section 10.4.6.1 is effective with the issuance of this letter.

Michael Shaw
Manager,
Materials, Joining and Laboratories Group
Stellantis N.V.

Frank M. Farber
Director
ASTM Test Monitoring Center

Attachment

c: https://www.astmtmc.org/ftp/docs/gas/sequenceiii/procedure_and_ils/IIIH/il22-3_iiih.pdf

Distribution: Email

Revises D8111-21a as amended by Information Letters 22-1 and 22-2

10.4.6.1 Use the U, L, Over Range, and Under Range values shown in **Table 65** for the QI calculations.