

Test Monitoring Center

Carnegie Mellon University 6555 Penn Avenue, Pittsburgh, PA 15206, USA http://astmtmc.cmu.edu 412-365-1000

Memorandum: 09-043

Date: October 16, 2009

To: Bill Buscher, Chairman, Sequence IVA Surveillance Panel

From: Richard E. Grundza

Subject: Sequence IVA Semiannual Report: April 1, 2009 through September 30, 2009


The following is a summary of Sequence IVA reference tests that were reported to the Test Monitoring Center during the period April 1, 2009 through September 30, 2009.

Lab/Stand Distribution

	Reporting Data	Calibrated as of September 30, 2009	
Number of Laboratories:	3	3	
Number of Test Stands:	7	6	

The following chart shows the laboratory/stand distribution:

Laboratory/Stand Distribution




The following summarizes the status of the reference oil tests reported to the TMC:

Calibration Start Outcomes	TMC Validity Codes	No. of Tests
Operationally and Statistically Acceptable	AC	8
Operationally Valid, Statistically Unacceptable	OC	2
Operationally Invalid, Laboratory Judgement	LC	2
Total		12


Calibrations per start, lost tests per start and rejection per start rates are summarized below:

Calibration Attempt Summary



The calibration per start rate has increased since last period. The lost test per start rate has decreased since last period. The rejected test per start rate has increased this period.

Rejected Test Rate for Operationally Valid Tests



Two tests failed acceptance criteria. Both tests failed for stand severity Shewhart alarms in the severe direction.

There were no LTMS Deviations written this period. Since its introduction in 1999, there has been one Sequence IVA LTMS deviation.

There was one QI Deviation written this period. The QI deviation was issued for load control generating a QI value below 0.000. A total of 25 QI deviations have been written to date.


Lost Test Summary

Two tests were lost this period. The reasons for the lost tests are tabulated below:

Reasons for Lost Test(s)	Number
Broken engine mounts	1
Humidity ran out of specification	1

Aborts and operationally invalid tests, reported by laboratory, are summarized in the following chart:

Lost Test Distribution



Severity and Precision Analysis

Below is a summary of the average Δ /s, pooled standard deviation, and average Δ in reported units for the tests reported during this report period. Also below is a summary of the average Δ /s value, by laboratory.

Industry Severity Summary			
Parameter	Average Δ/s	Pooled standard deviation (degrees of freedom)	Average Δ , in micrometers
ACW	1.272	8.33 (df = 8)	10.60 μm

ACW Results, by Laboratory	
Laboratory	Average Δ/s
A	1.570
B1	1.071
F	-0.414

The industry control chart for severity has been in severe alarm the entire period. Precision was in control for the period. (see Figure 1).

The industry was severe for the period (see Figure 2) with an average Δ /s result of 1.272 which equates to 10.60 μ m in reported units. The pooled standard deviation for the period is 8.33 μ m, which has improved when compared to the last period, and compares well with overall historical performance (see Figure 3).

Hardware

No hardware changes were made this period.

One lab visit was conducted this period. No discrepancies were identified during this visit.

Information Letters

Information Letters 09-1 and 09-2 were issued this period. The subject of these information letters can be found in the Industry Timeline, Figure 4.

Reference Oils

Oil	TMC Inventory, in gallons	TMC Inventory, in tests (4gal/test)	Laboratory Inventory, in tests	Estimated life	
1006	41	10	7	1 month or less ¹	
1006-2	4,050	1012	5	3+ years ¹	
1007^2	252	63	6	3+ years ¹	
1009	561	140	4	3+ years ¹	

¹ Multiple test area reference oil; total TMC inventory shown.
² Cannot be reblended.

REG/reg

Attachments

F. M. Farber, TMC

J. A. Clark, TMC

Sequence IVA Surveillance Panel

ftp://astmtmc.cmu.edu/docs/gas/sequenceiv/semiannualreports/IVA-10-2009.pdf

Distribution: Electronic Mail

List of Figures

- Figure 1 graphically presents the Industry control charts for ACW and also the CUSUM delta/s plot (by count in completion date order) of average camshaft wear for operationally valid tests.
- Figure 2 graphically presents a historic perspective for ACW mean delta/s by report period.
- Figure 3 graphically presents a historic perspective for ACW pooled standard deviations by report period.
- Figure 4 is the Sequence IVA Timeline, created to track changes in test hardware and operations.

Figure 1
SEQUENCE IVA INDUSTRY OPERATIONALLY VALID DATA

AVERAGE CAM WEAR




Figure 2 - Sequence IVA Reference Oil Data Average Camshaft Wear





Figure 3 - Sequence IVA Reference Oil Data Average Camshaft Wear



Date	Торіс	Information Letter
	SEQUENCE IVA TEST LTMS ESTABLISHED BY SURVEILLANCE PANEL	
	CALIBRATION STATUS RESUMED	
	DRAFT 4 OF TEST PROCEDURE ISSUED. INCORPORATED JACKETED ROCKER COVER, CONTROLLED FLOW OF FRESH AIR TO ROCKER COVER, AND OIL CYLINDER HEAD AS OIL	
	TEMPERATURE CONTROL POINT.	00-1
	REVISED DATA DICTIONARY AND REPORT FORM SET (VERSION 20000126) GOES INTO EFFECT.	00-2
	REVISED DOUBLE-FLUSH COOLANT CONTROL REQUIREMENTS EFFECTIVE	00-3
	REVISED ENGINE STARTING PROCEDURE EFFECTIVE	00-3
	ELIMINATE THE REQUIREMENT FOR LINEAR RAMPING OF TRANSIENT PARAMETERS	00-3
	REVISED OIL SAMPLING PROCEDURE	00-3
	REVISED DOUBLE-FLUSH OIL DRAIN REQUIREMENT	00-3
	REVISED COMPRESSION TEST REQUIREMENTS	00-3
	NEW CAMSHAFT CLEANING REQUIREMENTS	00-3
	CAMSHAFT LOT RESTRICTIONS	00-3
7/22/2001	ROCKER COVER COOLANT FLOW MEASUREMENT & REPORTING	01-1
		_
5/24/2001	REVISED CYLINDER HEAD AND TEST ENGINE REPLACEMENT REQUIREMENTS	01-2
5/25/2001	REVISED TEST NUMBERING REQUIREMENTS	01-2
	REVISED ENGINE BREAK-IN SPECIFICATIONS	02-1
	UPDATED DRAFT STANDARD OF SEQUENCE IVA TEST PROCEDURE RELEASED	02-1
	REVISED CAMSHAFT MEASUREMENT PROCEDURES	02-2
	STAND CALIBRATION REQUIREMENT REVISIONS	02-3
	STAND INSTRUMENTATION CALIBRATION REQUIREMENT REVISIONS	02-3
	REVISED OIL SAMPLE TAP LOCATION	02-3
	LUBRICATION OF CAMSHAFT DURING INSTALLATION	02-4
	CAMSHAFT BEARING BORE MEASUREMENTS ELIMINATED EXCEPT FOR INITIAL ENGINE BUILD	04-1
	NEW SOLVENT SPECIFICATIONS	04-1
7/19/2004	REVISED PRECISION DEFINITIONS	04-1
	REVISED REPLACEMENT CRITERIA FOR CYLINDER HEADS AND ENGINES	05-1
11/19/2004	CLARIFIED SOLVENT SPECIFICATION REQUIREMENTS	05-1
11/19/2004	REVISED QI U&L VALUES FOR COOLANT OUTLET TEMPERATURE	05-1
	REVISED CALIBRATION FREQUENCY FOR INSTRUMENTATION CHANNELS	05-1
	ADDED SECTIONS AND ANNEX TO DEFINE ROLE OF TMC AND EXTEND CALIBRATION PERIODS FOR DONATED TEST PROGRAMS	05-1
6/8/2005	UPDATED PRECISION ESTIMATE	05-2
12/13/2005	ADDED TOLERANCES TO MEASUREMENT DEVICE LOCATIONS	05-3
	INCREASED NUMBER OF RUNS ALLOWED ON BLOCK AND HEADS	05-3
	ADDED/REVISED SCHEDULE FOR OIL COOLER, PCV VALVE AND COOLANT SYSTEM CLEANING/REPLACEMENT	05-3
12/13/2005	ADDED LIMITS ON LOST OPERATIONAL DATA	05-3
12/13/2005	REVISED FUEL TEMPERATURE CONTROL LIMITS	05-3
12/13/2005	REVISED TORQUE CONTROL STRATEGY	05-3
02/16/2006	REVISED WEAR MEASUREMENT TECHNIQUES	06-1
02/16/2006	ADDRESSED EDITORIAL CHANGES	06-1
2007/11/16	UPDATED REFERENCE OIL TARGETS (N = 29) REFERENCE OIL 1009	
2008/11/20	CLARIFIED CALCULATIONS FOR QI WHEN MISSING OR BAD QUALITY DATA ARE ENCOUNTERED	08-1
	CORRECTED TYPOGRAPHICAL ERROR	08-1
2009/06/18	DROPPED VALVE SPRING FREE LENGTH AND OUT OF SQUARE MEASUREMENTS, ADDED VACUUM CHECKS TO ASSEMBLED CYLINDER HEAD	09-1
	ADDED MONITORING OF ROCKER COVER INLET AND OUTLET TEMPERATURES, ENGINE COOLANT PRESSURE AND FRONT COVER FRESH AIR FLOW	09-1

Memo 09-043 Page 11

2009/06/18	INCREASED THE NUMBER OF ALLOWED RUNS ON CYLINDER HEADS AND BLOCKS	09-1
2009/09/22	DELETED REQUIREMENT TO MAIL HARD COPY TEST REPORT TO TMC	09-2