Sequence VIE FEI 2 Response Task Force December 12, 2017 @ 9:00-10:00 CST

Toll-free dial-in number (U.S. and Canada): (866) 588-1857

Conference code:

1908975

1. Roll Call (start 9:00 CST)

1.1. Membership

1.1.1 Adrian (present), Andrew(present), Bill, Charlie, Cliff(present), Dan(present), Jerry, Katerina(present), Todd(present), Rich(present), Amol(present), Mark (Haltermann) (present).

2. New Business

SCOPE: The Task Force will review data, chemical analysis for the 109 hour aging, and other factors for the VIE test looking for a root cause for a response shift affecting FEI 2.

2.1. VIE/F FEI 2 Severity

- 2.1.1. Presentation Update
- Stats group is exploring the option of changing SAs given that there is a severity trend across all labs.
- Todd will review if there is a correlation between BSFC numbers and references severity
 - 2.1.2. Engine Tear Down Update
 - 2.1.3. Haltermann Fuel Update
- Additive is sourced from the same supplier for both Nixon and Sterling locations.
- The mixing amounts are calculated previous to filling the takers, then mixed with the fuel as the tanker is filled. Samples are not taken or analyzed after filling the tanker.
- There is a possibility Haltermann can implement a large tank (~350K gallons or ~14 months supply) to blend large batches of fuel to supply all labs with the same batch and therefore reduce variability.

<u>www.astmtmc.cmu.edu</u> - /ftp/docs/gas/sequencevi/minutes/VIE Engine Photos/Failing Reference/

<u>www.astmtmc.cmu.edu</u> - /ftp/docs/gas/sequencevi/minutes/VIE Engine Photos/Four run Engine/

3. Next Meeting

3.1. TBD

4. Meeting Adjourned