

Sequence X Procedure Review Task Force Teleconference 29th August 2018

Written By: Al Lopez

1. The group re-visited the wording for section 8.20.7.
 - a. Demetrius presented wording on the LZ lab practice at the previous meeting that required the rotation of the chain prior to measurement. Other labs have their own practice of seating the chain. We agreed to word the procedure to allow labs to use their own practice. Jason to re-write the section for review before publishing.
2. The figure for intercooler tubing A9.13 needs the addition of a thermocouple. Jason to ask Ron to update the drawing.
3. Rich Grundza has requested a section in the procedure describing load measurement. The LSPI procedure will be reviewed and possibly copied.
4. All Labs running tests with no issues.
5. The availability of the Frozen boost intercoolers is still a concern. Several options were discussed.
 - a. Jason has contacted Frozen Boost supplier but they have not been responsive. The manufacture of the intercooler is in China – Shauman Intercoolers. WE agreed to make an effort to contact the manufacturer directly.
 - b. CSX Racing and Silicone Intake offer intercoolers. We may need to change supplier.
 - c. A suitable intercooler needs to meet the pressure drop specified in the procedure. Not all labs are using the same units now.
 - d. This issue will be an ongoing concern but will not hold up the procedure review and publication.
6. Jason and I met with Terry Bates earlier that morning. Terry requested all edits and rewording to be completed before he begins the final copy of the procedure. Terry is on holiday and will be available on the 19th for discussion and presentation from us of the final document.
7. The next task for meeting will be in two weeks on September 12th.