




## Test Monitoring Center

6555 Penn Avenue  
Pittsburgh, PA 15206-4489  
(412) 365-1000

**MEMORANDUM:** 05-063

**DATE:** October 3, 2005

**TO:** Ed Callis, Chairman, ASTM Section D02.B0.06

**FROM:** Richard E. Grundza 

**SUBJECT:** Two-Stroke Cycle Reference Test Status from April 1, 2005 through September 30, 2005

### Status

There was no Ring Sticking (D 4857), Lubricity (D 4863), or Preignition (D4858) reference test activity for this ASTM period. For a summary of the most recent reference activity, please refer to TMC Memorandum 05-015. This summary is also available from the TMC web site at: <ftp://ftp.astmtmc.cmu.edu/docs/gas/tc/semiannualreports/>.

REG/reg

Attachments

c: F. M. Farber, TMC  
J. L. Zalar, TMC  
Two-Stroke Cycle Mailing List  
<ftp://ftp.astmtmc.cmu.edu/docs/gas/tc/semiannualreports/tc-10-2005.pdf>

Distribution: Email