

L-33-1 Information Letter No. 07-4 Sequence No. 11 November 14, 2007

ASTM consensus has not yet been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.

TO: L-33-1 Mailing List

SUBJECT: Revised Start-up Procedure

At the November 7, 2007 L-33-1 Surveillance Panel meeting, the panel revised the start-up procedure. A revised Section 11.1.3 of Test Method D 7038 is attached.

This change is effective the date of this information letter.

Dale Smith Chairman L-33-1 Surveillance Panel

L. Jalar

John L. Zalar Administrator ASTM Test Monitoring Center

Attachment

c: <u>ftp://ftp.astmtmc.cmu.edu/docs/gears/1331/procedure\_and\_ils/il07-4.pdf</u>

Distribution: Email

11.1.3 Start the driving motor and immediately accelerate the motor to  $2500\pm25$  r/min. Record the time and initial oil temperature at the time of the driving motor start up.