

Test Monitoring Center

@ Carnegie Mellon University 6555 Penn Avenue, Pittsburgh, PA 15206, USA http://astmtmc.cmu.edu 412-365-1000

L-37-1 Information Letter 20-3 Sequence Number 008 November 12, 2020

ASTM consensus has not been obtained on this information letter. An appropriate ASTM ballot will be issued in order to achieve such consensus.

TO: L-37-1 Surveillance Panel

SUBJECT: Removal of Section X1.1.1

During a February 13th, 2019 surveillance panel meeting, the members unanimously voted to remove section X1.1.1 from the test procedure. Information Letter 19-01 was issued following this meeting, but mistakenly did not capture the removal of section X1.1.1.

The revisions to Test Method D8165 are shown in the attachment. The changes are effective with the date of this information letter.

Robert Slocum Chairman

L-37-1 Surveillance Panel

Frank Farber Director

ASTM Test Monitoring Center

Frank m Faiber

Attachment

c: http://www.astmtmc.cmu.edu/ftp/docs/gear/1371/procedure_and_ils/il2003_L371.pdf

Distribution: Email

(Revises Test Method D 8165-20)

Delete section X1.1.1:

X1.1 *General*:

X1.1.1 The Gleason Works gearset hardware has not yet been approved for the Canadian test.

Renumber sections X.1.1.2 and X1.1.3, as X1.1.1 and X.1.1.2, accordingly.