



A Program of ASTM International

Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

MEMORANDUM: 24-007

DATE: May 14, 2024

TO: Nick Schaup, Chairman, L-37 Surveillance Panel

FROM: Dylan Beck *Dylan Beck*

SUBJECT: L-37 Rater Calibration from October 1, 2023, through March 31, 2024

Attached is a summary of L-37 rater calibration activity this period.

DJB/djb/mem24-007.djb.doc

cc: Jeff Clark

Sean Moyer

L-37 Surveillance Panel


<https://www.astmtmc.org/ftp/docs/gear/l37rc/semiannualreports/l37rc-04-2024.pdf>

Distribution: email

L-37 Rater Calibration

	Reporting Data	Calibrated on 3-31-24
Number of Labs	4	4
Number of Raters	12	12

BY-LAB RATER
DISTRIBUTION



13:34:09 09APR2024



Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

Test Distribution by Validity

		Totals	
		Last Period	This Period
Accepted for calibration	AC	18	15
Rejected (Mild)	OC	1	3
Rejected (Severe)	OC	4	4
Rejected (Multiple)	OC	0	0
Rejected (Precision)	OC	0	2
Workshop data	AG	4	10
Total		27	34

L-37 Rater Calibration

			RIDG		RIPP		SPIT		WEAR	
Rater		N	Avg Yi	STD*						
AB		12	0.381	0.939	0.164	0.972	-0.107	0.429	0.577	0.480
AD		4	-0.229	0.766	0.090	0.330	0.338	0.272	-0.462	1.594
AE		12	-0.499	1.336	0.135	0.896	0.012	0.348	-0.279	1.424
AF		12	-0.145	0.969	-0.205	0.936	0.031	0.398	-0.274	0.406
AG		16	-0.021	1.456	0.272	0.678	-0.052	0.485	0.107	1.027
AH		8	-0.558	1.140	-0.605	1.425	0.393	1.466	0.107	1.843
BB		4	0.013	0.375	-0.276	0.447	-0.008	0.432	-0.351	0.904
I		8	-0.361	0.638	-0.111	1.090	-0.056	0.340	0.097	0.803
Q		4	0.222	0.605	0.396	0.842	0.032	0.394	-0.301	0.876
T		4	0.117	0.830	-0.361	0.549	0.410	0.463	0.306	0.724
V		4	-0.025	1.126	0.256	0.652	0.011	0.292	-0.097	0.910
Z		4	0.286	0.450	0.025	0.722	0.130	0.358	-0.174	0.335
ALL		92	-0.101	1.056	0.003	0.890	0.051	0.569	-0.007	1.027

* Due to the small number of ratings per pinion, the standard deviation of the Yi values is given in place of a pooled standard deviation.



Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

RIDGING

Severity as Measured by Delta/s



13:34:09 09APR2024



Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

RIPPLING

Severity as Measured by Delta/s



13:34:09 09APR2024



Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

SPITTING

Severity as Measured by Delta/s



13:34:09 09APR2024



Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

WEAR

Severity as Measured by Delta/s



13:34:09 09APR2024



Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

RIDGING

Precision as Measured by Yi STD



13:34:09 09APR2024



A Program of ASTM International

Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

RIPPLING

Precision as Measured by Yi STD



13:34:09 09APR2024




A Program of ASTM International

Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration



13:34:09 09APR2024



A Program of ASTM International

Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

WEAR

Precision as Measured by Yi STD



13:34:09 09APR2024



A Program of ASTM International

Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

SUMMARY OF SEVERITY & PRECISION

Severity

RIDG exceeded the action limit in the severe direction this period but ended the period within the limits. SPIT ended the reporting period exceeding the action limit in the severe direction.

Precision

All parameters remained within limits throughout the period.

Industry rater control charts follow.



Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA


www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

RIDGING

LTMS Severity Analysis



A Program of ASTM International

Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

RIPPLING



A Program of ASTM International

Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

SPITTING



A Program of ASTM International

Test Monitoring Center


203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

WEAR



A Program of ASTM International

Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org


412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

RIDGING

LTMS Precision Analysis



A Program of ASTM International

Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA


www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

RIPPLING

LTMS Precision Analysis



A Program of ASTM International

Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA


www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

SPITTING

LTMS Precision Analysis



09APR24:14:43



A Program of ASTM International

Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA


www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

WEAR

LTMS Precision Analysis



Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA


www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

RIDGING

CUSUM Severity Analysis



09APR24:14:44



A Program of ASTM International

Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA


www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

RIPPLING

CUSUM Severity Analysis



A Program of ASTM International

Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA


www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

SPITTING

CUSUM Severity Analysis



09APR24:14:44



Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA


www.astmtmc.org
412-365-1000

L-37 Rater Calibration

L-37 RATER CALIBRATION INDUSTRY OPERATIONALLY VALID DATA

WEAR

CUSUM Severity Analysis



Test Monitoring Center

203 Armstrong Drive, Freeport, PA 16229, USA

www.astmtmc.org
412-365-1000