


<b>Laboratory:</b> SR	<b>Stand No:</b> 04	<b>Stand Run No.:</b> 0365
<b>Oil Code:</b> 67393		
<b>Test Hardware:</b> Nonlubrited	<b>Test Version:</b> Standard	

L37 Gear Set Pattern

Before Test Contact Pattern



After Test Contact Pattern

